

Dutchess County Balefill
Post-Closure Monitoring & Maintenance

Photo Log: Spring area near Wappinger Creek
bank



Photo #1 – Representative view of spring area near bank of Wappinger Creek –May 2013



Photo #2 – Representative view of spring area near bank of Wappinger Creek –June 2013



Photos #3 & #4 – Representative views of spring area near bank of Wappinger Creek – September 2013



Photos #5 & #6 – Representative views of spring area near bank of Wappinger Creek – December 2013

NOTE: While a spring-like flow continues to emanate from the bank area along the Wappinger Creek, no orange discoloration or staining was detected in spring area during the fourth quarter 2014 inspection.