

DAILY INSPECTION REPORT

Site Code #: 3-44-046	Date: 16-Dec-2013	Report #: OR121613
------------------------------	--------------------------	---------------------------

Site Name: Nyack MGP
Location: Nyack, Rockland County
PRP Proj. Mgr.: Maribeth McCormick
DEC Proj. Mgr.: Elizabeth Lukowski
Consultant Proj. Mgr.: James Edwards
Proj. Contr.: “2 guys with a boat”
Site Phone & Fax: N/A

	AM	PM
Weather	Sunny	Sunny
Temperature	28	30
Wind Direction	From the W 0-5 mph	From the W 5-10

Description of work performed by contr. this report period:

- This date “2 guys with a boat” collected sediment samples in the OU2 area of the Nyack MGP site. Push core samples were collected from a modified 24’ pontoon boat.
- Samples SD-70; SD-71; and SD-72 were collected. The following was noted:
SD-70 4’ recovery, top 6” was wet black silt, remainder of the sample was moist black fine sand, shells, trace organics. Organic odors noted.
SD-71 1.5’ recovery, top of sample contained wet black silt, remainder was moist black fine sand, shells, organic odor. Multiple attempts at this location had refusal on wood structure.
SD-72 2’ recovery, wet black silt, fine sand, shells, organics. Some MGP odor noted on the top of the sample.

Discussions/comments regarding visitors, contractor and/or engineer:

- This dates sediment sampling occurred to further delineate the northern limits of remedial dredging near the Nyack Boat Club.
- SD-70 was collected using a vibracore (but pushed manually, contractor was unable to get motor for vibracore to work). SD-71 and SD-72 were collected using a “push core” method, a lexan tube was manually pushed into the river sediment.
- There was no sheen or NAPL noted in any of the samples collected this date.
- No sheens were noted in the river during sample collection this date.
- Consultant stated they are awaiting a Westchester County Permit to perform future work at the site

including decommissioning 3 wells, and the collection of 7 pre-characterization samples via sonic drilling.

Sampling and Analyses:

- All soils were field characterized.
- Soil samples were collected at each location, in zones: 0-.5'; .5'-1'; and 1'-2'.
- All samples were sent to Test America of Canton, Ohio for analysis with a three day turnaround.

Major Issues	Description & Reason

Health & Safety:

Level of protection: Normal.

Is the level of protection in conformance with the approved Health & Safety Plan? Yes.

List of deviation's.

Are atmospheric monitoring results acceptable? Yes.

Site Visitors	Representing	Entered Exclusion Zone
James Edwards	GEI	
Jerry Peake	GEI	
Alex Roico	GEI	
Dave Bailey	2 guys with a Boat	
Lenny	2 guys with a Boat	

Site Representative: David Herman

Date: December 16, 2013

Representative's signature: