NEW YORK STATE DEPARTMENT OF ENVIRONMENT 1, CONSERVATION Division of Environmental Remedi

## Division of Environmental Remea Inactive Hazardous Waste Site Operations and Maintenance Review Report

				Form Date 96 10.0
Site Name: Marx Residen		Class:	2	Number: 3-60-024
O&M Funding Source:	D State Superfund	Federal Superfund	Municipal	Responsible Party
O&M Information: O&	M Start: 9401	End:	Annual Cost:	: \$2,395
Interim Remedial Measures/Operable Units in O&M Phase:				
Drum Removal		Removal	🛛 Tank R	
□ Cap/Cover		ainment Structure		
Groundwater Recove	•	hate Collection/Treatment		Extraction/Treatment
Air Sparging/Stripper		tment/Filtration Plant/System	L Potable	e Water Supply/System
Institutional Controls:	· · ·	Discharge Permit	🗖 Depa	artment of Health Sampling
□ Other:		-	_	
<b>O&amp;M</b> Review Information				
Reports: October 1997 i	ndoor air and soil vapor s	ample results.		
40/0/07				
Inspection: <u>10/8/97</u>				
Sampling: <u>1018197</u> Other:				
Conclusions:	· · · · · · · · · · · · · · · · · · ·	<u>, , , , , , , , , , , , , , , , , , , </u>		
Remedy Effective?	′es □ No: Indoor air lev	vels for PCE remain below the	e recommende	d level of 0.015 ppm
-				
ROD Compliance?  Yes No: NIA				
Consent Order Compliance?  Ves N/A				
Other:				
Recommendations: NYSDOH has recommended that no further air monitoring is required.				
·				
ROD/Consent Order Modifications? □ No □ Yes (per above) Reclassify the Site?  No □ Yes → Class:				
Comments: Drinking water issues remain to be addressed at this site.				
	<u></u>			
Project Manager:	2/25/	Reviewer:		
Signature	2/25/ Date			Date
Ronnie E. Lee, P.E. BHS	SC 7-0927	Gerald J. Rider, Jr.		
Name Region	n or Bureau Telephone	Name	Region or Bure	eau Telephone