

TENNESSEE GAS PIPELINE COMPANY
COMPRESSOR STATION 254
NASSAU, NEW YORK

O&M ACTIVITY LOG FORM

Personnel Performing O&M Activity

L. H. Grebert

Date:

7/7/04



Drainline A Excavation – Provide Description of Activity (include sketch as attachment)

NO ACTIVITIES AFFECTING DRAINLINES

Drainline Component Removed? (Yes/No)

Drainline Component and Surrounding Soil Disposed? (Yes/No) (Attach Manifest)

Repairs Made to Exposed Drainlines? (Yes/No) Describe:



Air Receiver Tank Cap Excavation – Provide Description of Activity (include sketch as attachment)

NO CHANGES - CAP NOT DISTURBED

Excavation Below Cap Performed? (Yes/No)

Excavated Materials Disposed Off-Site? (Yes/No) (Attach Manifest)

Cap Restored to Original Condition? (Yes/No) Describe: N/A



Drainage Area A Inspection – Rip-Rap Providing Adequate Erosion Protection? (Yes/No)

Repairs Made? (Yes/No) Describe:

NO CHANGES



Service Road Area – Areal Coverage and Thickness of Stone Layer Adequate? (Yes/No)

Repairs Made? (Yes/No) Describe:



Groundwater Monitoring – Groundwater Sampling Performed? (Yes/No) (Attach Summary Report and Analytical Results) MONITORING WELL ABANDONED ON 5/13/03



Surface Water Monitoring – Surface Water Sampling Performed? (Yes/No) (Attach Summary Report and Analytical Results) ONE-TIME SAMPLE COMPLETED 4/30/97

Grebert, Lawrence H (Larry)

From: Grebert, Lawrence H (Larry)
Sent: Thursday, August 12, 2004 1:53 PM
To: Kolanko, Wayne D
Cc: Morawski, Stephen H
Subject: Excavation near Air Receiver Tank area at Station 254

Wayne: FYI

Per the O&M Plan for soil remediation work at Station 254 (section 3.2), I talked with Steve Morawski on 8/10/04 before beginning excavation work in the air receiver tank area. The low-permeability cap will not be disturbed or exposed during the excavation work, and no excavation will take place beneath it.

*Larry Grebert
Operations Supervisor
Nassau Area - District 254
5035 Route 66
Nassau, NY 12123
(518) 766-3611 x-2023*

8/12/2004