NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

<u> </u>	Form Date 96.10.01
Site Name: Korkay, Incorporated	Class: 2 Number: 5-18-014
O&M Funding Source: X State Superfund ☐ Federal	Superfund Municipal Responsible Party
O&M Information: O&M Start: 9811 End:	Annual Cost: \$
Operable Units in O&M Phase:	
☐ Drum Removal ☐ Soil Removal	□ Tank Removal
☐ Cap/Cover ☐ Containment Str	ucture X Fence/Security
☐ Groundwater Recovery/Treatment ☐ Leachate Collection	ction X Vapor Extraction/Treatment
X Air Sparging System ☐ Pre-treatment P	lant System Potable Water Supply/System
X Other: Groundwater Monitoring	
_ ·	scharge Permit
	uivalent y not a SPDES.
O&M Review Information:	
Reports: Operation & Maintenance Plan (January 1999), Reme	dial Construction Certification Report (May 2000)
Inspection: Done monthly, at a minimum. Last Inspection 7/13/0	0.
	00. Results show that confirmatory soil sampling can be
done at any time. Site Groundwater Monitoring wells (
Other: Mowing is done by Division of Operations.	
Conclusions:	
Remedy Effective? X Yes No: Concentration in the soil building demolition were the major remedial actions. The SVE procontamination.	I vapor gas has decreased. Contaminated soil removal and ogram is an IRM to address any residual subsurface soil
ROD Compliance?	
Consent Order Compliance? ☐ Yes ☐ No: NA	
Othor	
Other:	
Recommendations: Next review 07/2001. Based on air result	s the SVE has successfully treated the soil. Confirmatory
soil sampling will be the final proof. We continue to run the SVE	with the air sparger because the VOC concentrations in the
groundwater are decreasing at an impressive rate. The groundware to expected diminished treatment returns during the freezing	
late November to March/April.	months, the over/all opurge system will not be full from
Grundwater pulled in by the SVE is two	tel through cerbon and discharged to
Starm sewer.	
PODICe and Order Medification C. F. No. F. Ver	Dada if the City II No. V Veg. Olean 4
ROD/Consent Order Modifications? No Yes (per above)	Reclassify the Site □ No X Yes → Class: 4
	00. The only parts of the treatment trailer being used are the
SVE piping, blower and carbon vessels. We think we have met s	
running the air sparger. The DEC is overseeing the operation of the	
meet standards. Once the SVE unit is turned off, there will need to	•
treatment trailer will need to be cleaned, disconnected, and moved	I to storage.
Reclass (to a 4) package has been submitted by BCS to BHSC.	
toku 100 hang 07/21/00	Reviewer: The last 1/21/10
Signature Date John R. Strang Haz. Site Control (518) 457-0927	Gerald J. Rider, Jr. Haz. Site Control (518) 457-0927
Name Region of Bureau Telephone	Name Region of Bureau Telephone