

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/02/02

time 16:00

monthly sample taken: 12/12/01
next 01/09/02

by telephone

site visit

Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	Operating	<u>Not operating, had to be reset</u>	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber

4.81 /H2O

W4	Operating	Not operating, had to be reset	Not operating#
----	-----------	--------------------------------	----------------

junction enabled @ 4:13 pm. Q = 17 gpm.

Effluent Collection Sump Pump Chamber

High Level Alarm? NO! 1.137 H2O

W5	Operating	Not operating, had to be reset	<u>Not operating"</u>
----	-----------	--------------------------------	-----------------------

" Pumped down.

Discharge Pumps

Equalization Tank level 11

<u>P201</u>	OPERATED: @ Site	while on Computer	N/A
<u>P202</u>	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems?

@ 14 4:15 pm. w/ W4 on bypass and enabled

Over

Cell Levels LT401 2.723 LT402 0.687 LT403 0.723 LT404 2.891
 LT405 2.216 LT406 3.454 LT407 2.939 LT408 2.340
 LT409 2.402 LT410 2.507 LT411 2.429 LT412 4.398

Discharge to Polishing Pond? YES NO N/A
Overflow into Polishing Pond Standpipe? YES NO N/A
Discharge to Feeder Canal? YES NO N/A

Signature JR Straney

time: left site or signed off 16:19

comments Need to clean incoming flow meter. - Now
working.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar Apr-Jun

Jul-Sep

Oct-Dec

Date 01/03/02

time 9:20 10:39

monthly sample taken: 01/09/02

f. h.

by telephone

site visit

Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber 4.81 /H2O

W4	<u>Operating</u>	Not operating, had to be reset	Not operating#
#	<i>on Bypass</i>	<i>Dis-enabled @ 10:41.</i>	

Effluent Collection Sump Pump Chamber High Level Alarm? yes. 4.83/H2O

W5	Operating	Not operating, had to be reset	Not operating"
----	-----------	--------------------------------	----------------

"

Discharge Pumps

Equalization Tank level 24

went to 25 9:23

Σ Q
604
1901 *locked out*
1451
648

P201	OPERATED: @ Site	<u>while on Computer</u>	<u>N/A</u>
P202	OPERATED: @ Site	<u>while on Computer</u>	N/A
P203	OPERATED: @ Site	<u>while on Computer</u>	<u>N/A</u>
P204	OPERATED: @ Site	<u>while on Computer</u>	<u>N/A</u>

problems?

31 @ 9:30
36 @ 9:34
45 @ 9:44
49 @ 9:49
50 @ 9:50
49 @ 9:52
44 @ 10:00

- pumps on @ 9:51.

38 @ 10:10
interrupted @ 10:13 Over
21 @ 10:39
20 @ 10:40
Pumps off @ 10:41

Cell Levels LT401 2.678 LT402 0.758 LT403 0.768 LT404 2.174
 LT405 2.262 LT406 3.381 LT407 2.948 LT408 2.381
 LT409 2.428 LT410 2.531 LT411 2.446 LT412 4.363

Discharge to Polishing Pond? YES NO N/A

Overflow into Polishing Pond Standpipe? ^{Possibly} YES NO N/A

Discharge to Feeder Canal? YES NO N/A

Signature John Strang

time: left site or signed off 10:42

comments _____

Definitely need to clean influent flow meter, and discharge pump flow meters.

Left WC off.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/04/02

time 10:12

monthly sample taken: _____

up coming. 01/09/02

by telephone

site visit

Power Meter Reading _____ time _____

NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber

4.81 /H2O

W4	Operating	Not operating, had to be reset	<u>Not operating#</u>
----	-----------	--------------------------------	-----------------------

Bypass not enabled. Enabled @ 10:14

Effluent Collection Sump Pump Chamber

High Level Alarm? Yes. 4.83 /H2O

W5	<u>Operating</u>	Not operating, had to be reset	Not operating"
----	------------------	--------------------------------	----------------

"

Discharge Pumps

Equalization Tank level 0

P201	OPERATED: @ Site	while on Computer	N/A
P202	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems? _____

7 @ 10:20

Over

Cell Levels LT401 2.678 LT402 0.780 LT403 0.815 LT404 2.130
 LT405 2.227 LT406 3.564 LT407 2.949 LT408 2.351
 LT409 2.409 LT410 2.508 LT411 2.434 LT412 4.361

Discharge to Polishing Pond? YES NO N/A

Overflow into Polishing Pond Standpipe? YES NO ~~N/A~~ *unknown*

Discharge to Feeder Canal? YES NO N/A

Signature JKS/mjg.

time: left site or signed off 10:20 - last signal. signed off w/ w4 established.

comments Clean the Flow Meters.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar Apr-Jun

Jul-Sep Oct-Dec
monthly sample taken: _____
to be taken 01/09/02

Date 01/07/02 time 15:36

by telephone

site visit Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<u>Operating</u>	Not operating, had to be reset	Not operating*
W2	<u>Operating</u>	Not operating, had to be reset	Not operating*
W3	Operating	<u>Not operating, had to be reset</u>	Not operating*

* _____

Subsurface Collection Trench Sump Pump Chamber _____ /H2O

W4	<u>Operating</u>	Not operating, had to be reset	Not operating#
----	------------------	--------------------------------	----------------

on Bypass

Effluent Collection Sump Pump Chamber High Level Alarm? Yes. 4.83/H2O

W5	<u>Operating</u>	Not operating, had to be reset	Not operating"
----	------------------	--------------------------------	----------------

" _____

Discharge Pumps Equalization Tank level 2

4 when signed off @ 15:42

Locked out

P201	OPERATED: @ Site	while on Computer	N/A
<u>P202</u>	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

discharges to Cells 2,
problems? _____

Frozen

Cell Levels	LT401 2.303	LT402 0.190	LT403 0.235	LT404 2.103	2.1-2.3
	LT405 2.159	LT406 0.498	LT407 2.954	LT408 2.286	2.1-2.2
	LT409 2.338	LT410 2.444	LT411 2.355	LT412 3.758	2.3-2.4

Discharge to Polishing Pond? YES NO N/A

Overflow into Polishing Pond Standpipe? YES ^{guess} NO N/A

Discharge to Feeder Canal? YES NO N/A

Signature JLB fromy

time: left site or signed off 15:42

comments on 1/9/01

Clean flow meters. Get monthly samples.

Next Utility reading in 1/23/02 - its a Wednesday.

version date 10/29/01
558001Insp Form.wpd

used used used.

9/16/23

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/09/02

time 10:00

monthly sample taken: 1/9/02

Full clouds. Mid 30's.

by telephone

site visit

Power Meter Reading 96515 time 10:04
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

<i>5.5</i>	W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
<i>11.9</i>	W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
<i>10.2</i>	W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
<i>4/6.8</i>			<i>pumped down</i>	

Subsurface Collection Trench Sump Pump Chamber 4.72/H2O

W4	Operating	Not operating, had to be reset	Not operating#
----	-----------	--------------------------------	----------------

Effluent Collection Sump Pump Chamber High Level Alarm? NO 0.92/H2O

W5	Operating	Not operating, had to be reset	Not operating"
----	-----------	--------------------------------	----------------

Discharge Pumps Equalization Tank level 0.37

Lockdown

P201	OPERATED: @ Site	while on Computer	N/A
P202	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems? _____

②
Site

Cell Levels	LT401	2.303 2.22	LT402	0.190 0.41	LT403	0.235 0.45	LT404	2.103 2.07
	LT405	2.159 2.16	LT406	0.498 1.42	LT407	2.954 2.90	LT408	2.286 2.23
	LT409	2.338 2.28	LT410	2.444 2.38	LT411	2.355 2.29	LT412	3.758 2.44

Discharge to Polishing Pond? YES

NO

N/A

WS is pumped down.

Overflow into Polishing Pond Standpipe?

YES

NO

N/A

Discharge to Feeder Canal? YES

NO

N/A

Sampled @ WS pump chamber.

Signature _____

time: left site or signed off _____

4 to 5" of snow @ site
Road had been plowed.

comments

Clean Flow meters

@ 1105 Snow started - very steady!

Went to Discharge Point @ Feeder Canal - no flow. I could not hear

overflow @ Polishing Pond either. So, I turned on the Pump @ WS on bypass

to get flow out of Polishing Pond discharge pipe - No Luck. So I went

back to WS, ~~popped~~ popped the manhole cover off and using

a bucket took water samples from Manhole.

Done sampling @ 11:35 am.

11:45 - 12:05 Cleaned influent Flow meters.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/10/02

time 9:58

monthly sample taken: 01/09/02

by telephone

site visit

Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	Operating	<u>Not operating, had to be reset</u> @ 9:59	Not operating*
W2	Operating	Not operating, had to be reset	Not operating*
W3	Operating	Not operating, had to be reset	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber

4.81/H2O

W4	Operating	Not operating, had to be reset	<u>Not operating#</u>
----	-----------	--------------------------------	-----------------------

Not operating on bypass. Not pumping into EQ. TANK.

Effluent Collection Sump Pump Chamber

High Level Alarm? NO 2.482/H2O

2.669
@ 10:10 am.

W5	<u>Operating</u>	Not operating, had to be reset	Not operating"
----	------------------	--------------------------------	----------------

" NOT able to keep up w/ incoming flow. Has given light on.

Discharge Pumps

Equalization Tank level 21

22 @ 10:10

P201	OPERATED: @ Site	while on Computer	N/A
<u>P202</u>	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems? _____

Over

Cell Levels	LT401 ^{2.253}	LT402 ^{0.191}	LT403 ^{0.222}	LT404 ^{2.132}
	LT405 ^{2.231}	LT406 ^{0.770}	LT407 ^{2.961}	LT408 ^{2.359}
	LT409 ^{2.373}	LT410 ^{2.477}	LT411 ^{2.392}	LT412 ^{3.748}

Discharge to Polishing Pond? YES NO N/A *but my guess is yes.*

Overflow into Polishing Pond Standpipe? YES NO N/A

Discharge to Feeder Canal? YES NO N/A

Signature JRS

time: left site or signed off 10:12

comments W4 not operating on bypass 1/10/02
~~probably~~

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar Apr-Jun Jul-Sep Oct-Dec

Date 1/11/02 time 9:25 monthly sample taken: _____

by telephone

site visit Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	✓ Operating	Not operating, had to be reset	Not operating*
W2	✓ Operating	Not operating, had to be reset	Not operating*
W3	✓ Operating	Not operating, had to be reset	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber 4.81/H2O

W4 Operating Not operating, had to be reset Not operating#

on Bypass and enabled - but not pumping. So I disabled it.

Effluent Collection Sump Pump Chamber High Level Alarm? 4.83/H2O

W5 Operating Not operating, had to be reset Not operating"

Discharge Pumps Equalization Tank level 37

Locked out

P201	OPERATED: @ Site	while on Computer
P202	OPERATED: @ Site	while on Computer
P203	OPERATED: @ Site	while on Computer
P204	OPERATED: @ Site	while on Computer

N/A
N/A
N/A
N/A

problems? _____

Over

Cell Levels	LT401 ^{2.342}	LT402 ^{0.759}	LT403 ^{0.823}	LT404 ^{2.132}
	LT405 ^{2.241}	LT406 ^{1.734}	LT407 ^{2.960}	LT408 ^{2.365}
	LT409 ^{2.420}	LT410 ^{2.526}	LT411 ^{2.441}	LT412 ^{4.367}

Discharge to Polishing Pond? YES NO N/A *WS shows pumping*

Overflow into Polishing Pond Standpipe? YES NO N/A

Discharge to Feeder Canal? YES NO N/A

Signature *JL Strong*
 time: left site or signed off 9:37

comments W4 - disabled

File

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/16/02

time 14:52

monthly sample taken: _____

by telephone

site visit

Power Meter Reading _____ time _____

NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*

* _____

Subsurface Collection Trench Sump Pump Chamber 4.81 /H2O

W4	Operating	Not operating, had to be reset	Not operating#
----	-----------	--------------------------------	----------------

OFF (Disabled) - Enabled on Bypass - no such luck - Not pumping.
JL Strong

Effluent Collection Sump Pump Chamber High Level Alarm? Yes 4.83 /H2O

W5	Operating	Not operating, had to be reset	Not operating"
----	-----------	--------------------------------	----------------

" Shows green - operating.

Discharge Pumps Equalization Tank level 1

<i>Locked out</i> P201	OPERATED: @ Site	while on Computer	<u>N/A</u>
P202	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	<u>N/A</u>
P204	OPERATED: @ Site	while on Computer	<u>N/A</u>

problems? _____

Cell Levels LT401 2.725 LT402 0.15 LT403 0.18 LT404 2.08
 LT405 2.22 LT406 3.91 LT407 2.97 LT408 2.35
 LT409 2.34 LT410 2.44 LT411 2.37 LT412 3.78

Discharge to Polishing Pond? YES NO N/A UNKNOWN - W5 status is running.
 Overflow into Polishing Pond Standpipe? YES NO N/A
 Discharge to Feeder Canal? YES NO N/A

Signature J. Strang
 time: left site or signed off 15:06

comments ~~Let's go~~
W4 is not pumping - take off bypass. Plan for
recommission of Stone Haven.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

monthly sample taken: _____

Date 01/23/02

time 9:45

by telephone

site visit

Power Meter Reading 97534

time 9:49

NIMO account # 06352-56110 1-800-642-4272

Called. 9:53 ✓

meter # 55 971 553

Extraction Wells

W1	Operating	<u>Not operating, had to be reset</u>	Not operating*
W2	<u>✓</u> Operating	Not operating, had to be reset	Not operating*
W3	<u>✓</u> Operating	Not operating, had to be reset	Not operating*

Reset @ 10:25

*

Subsurface Collection Trench Sump Pump Chamber

4.72 /H2O

W4 Operating Not operating, had to be reset Not operating#

Turned off by Pass 10:31. Left power on. Fault light still on red.
01/23/02

Effluent Collection Sump Pump Chamber

High Level Alarm? 4.71 /H2O

W5 Operating Not operating, had to be reset Not operating*

OK, but no discharge @ Polishing Pond.

10:52
5 AM @
4.71

Discharge Pumps

Equalization Tank level 0.47

0.50 @ 10:10
2.04 @ 10:56

P201	OPERATED: @ Site	while on Computer	N/A
P202	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems? _____

Turned off @ 10:35. Nothing was tripped. Fan-heater was running.

Looked in Panel Over

Turned on to Drive @ 10:39. Power On, Motor running, No Fault. Went to check out flow @ Polishing Pond. The Reset worked! see Polishing Pond!

Cell Levels LT401 2.48 LT402 0.05 LT403 0.08 LT404 1.98
 LT405 2.17 LT406 0.59 LT407 2.93 LT408 2.24
 LT409 2.19 LT410 2.29 LT411 2.20 LT412 2.36

Discharge to Polishing Pond? YES NO N/A
 Overflow into Polishing Pond Standpipe? YES NO N/A
 Discharge to Feeder Canal? YES NO N/A

Signature JR Strang,
 time: left site or signed off 11:04

Duty
 8:30 - 12:00
 12:30 - 4:30
 8th - 11 Ft Ed. 2.5
 11 - 20.5 Karkey ~~2.5~~
 Bodo?

comments W4 turned on Bypass @ 11:00 JRS

Karkey 12:40

Office Trailer 24272

Call Tom Thomson - able to move office trailer from Karkey to Kingsbury. need washer electrically.

Someone had been on site to take meter reading @ Treatment Trailer.

Site was secure. Trailer looked OK.. 12:43 John Strang. 1/23/02

version date 10/29/01
 558001Insp Form.wpd

11:10 - 11:21

Walked 546042 Marcan Dredge Spout.

Under light coat of snow. Drain still running.

No depressed spots. No visible sloughing.

JR Strang.

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar

Apr-Jun

Jul-Sep

Oct-Dec

Date 01/23/02

time 15:52

monthly sample taken: 1/9/02

by telephone

called in earlier today.

site visit

Power Meter Reading _____ time _____

NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*

*

Subsurface Collection Trench Sump Pump Chamber

4.81 /H2O

W4	Operating	Not operating, had to be reset	Not operating#
----	-----------	--------------------------------	----------------

enabled 15:52 15:56 Disconnected. No Reaction in EQ TANK. W4 is not pumping.

Effluent Collection Sump Pump Chamber

High Level Alarm? Yes 4.83 /H2O

W5	<u>Operating</u>	Not operating, had to be reset	Not operating"
----	------------------	--------------------------------	----------------

"

Discharge Pumps

Equalization Tank level 5

locked out

P201	OPERATED: @ Site	while on Computer	<u>N/A</u>
P202	OPERATED: @ Site	while on Computer	<u>N/A</u>
P203	OPERATED: @ Site	while on Computer	<u>N/A</u>
P204	OPERATED: @ Site	while on Computer	<u>N/A</u>

problems? _____

Over

Cell Levels LT401 2.351 LT402 0.103 LT403 0.126 LT404 2.019
 LT405 2.239 LT406 0.102 LT407 2.996 LT408 2.359
 LT409 2.29 LT410 2.40 LT411 2.32 LT412 3.675

Discharge to Polishing Pond? YES NO N/A
 Overflow into Polishing Pond Standpipe? YES NO N/A
 Discharge to Feeder Canal? YES NO N/A

Signature J. K. Strang

time: left site or signed off 15:57

comments W4 - to be solved!

Fort Edward Landfill

Site No. 558001

Washington County

Quarter Jan-Mar Apr-Jun Jul-Sep Oct-Dec

Date 01/30/02 time 16:25 monthly sample taken: _____

by telephone

site visit Power Meter Reading _____ time _____
NIMO account # 06352-56110 1-800-642-4272

Extraction Wells

W1	Operating	Not operating, had to be reset	Not operating*
W2	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*
W3	<input checked="" type="checkbox"/> Operating	Not operating, had to be reset	Not operating*

June @ 16:25

* _____

Subsurface Collection Trench Sump Pump Chamber 4.81 /H2O

W4	Operating	Not operating, had to be reset	<u>Not operating#</u>
----	-----------	--------------------------------	-----------------------

Effluent Collection Sump Pump Chamber High Level Alarm? Yes 4.83 /H2O

W5	<u>Operating</u>	Not operating, had to be reset	Not operating"
----	------------------	--------------------------------	----------------

” _____
Green.

Discharge Pumps Equalization Tank level 38

Locked out.

P201	OPERATED: @ Site	while on Computer	N/A
P202	OPERATED: @ Site	while on Computer	N/A
P203	OPERATED: @ Site	while on Computer	N/A
P204	OPERATED: @ Site	while on Computer	N/A

problems? _____