DAILY INSPECTION REPORT

Fort Edward Landfill (Site # 558001)

NYSDEC Division of Environmental Remediation			OPPORTUNITY Er		ent of nental ition	Contract No. DEC Insp. – DEC PM – Payson Long
Site Location: 48 Leav	DEC FIN - Fayson Long					
	Weather Cor					Contractor Supt. –
General Description	Overcast	AM	Partly clo	udy	PM	Engineer PM – <u>Andy Vitolins</u>
Temperature	30 °F	AM	35 °F		PM	Engineer Insp. – Mike Merwin
Wind	0,0mph	AM	0.0 mp	h	PM	• -

Page 1 of 6

Date: 02/06/2023

Health & Safety If any box below is checked "Yes", provide explanation under "Health & Safety Comments".							
Were there any changes to the Health & Safety Plan?	Yes □	No ⊠	NA □				
Were there any exceedances of the perimeter air monitoring reported on this date?	Yes □	No □	NA ⊠				
Were there any nuisance issues reported/observed on this date?	Yes □	No ⊠	NA □				
Health & Safety Comments							

Health & Safety Comments

Work conducted with excavator along grade with potentially unstable material and ice and snow.

Summary of Work Performed Arrived at site: 0745 Departed Site: 1500

Removal of Ballast Baskets and Racking: Oversight of GreenSpark, O'Connor Construction (O'Connor) & I-Build:

- Mob to Site.
- Meet with GreenSpark, O'Connor, and I-Build work Crew.
 - Conduct Tailgate Safety Meeting.
 - Items discussed include Heavy Equipment, Slips-Trips-Falls, Stop-Work Authority, Cold Stress, and Dehydration.
- O'Connor crew sanded access roads to landfill cap and GreenSpark gate.
- GreenSpark, O'Connor, and I-Build worked to remove baskets filled or partially filled with stone from locations over and next to swales and down chutes.
 - o Crew worked in the SW area of the Site.
 - o I-Build crew utilized skid-steer to relocate solar panel module boxes to clear a path for the excavator.
 - o O'Connor crew utilized excavator and lift straps to remove all remaining baskets from the swales.
 - o Figure attached to indicate area where baskets have been removed.
- Demob from Site.

Equipment/Material Tracking If any box below is checked "Yes", provide explanation under "Material Tracking Comments". Were there any vehicles which did not display proper D.O.T. numbers and placards? Were there any vehicles which were not tarped? Were there any vehicles which were not decontaminated prior to exiting the work site? * Yes □ No □ NA ☑ Personnel and Equipment

Individual Trade **Total Hours** Company E-EIT Mike Merwin Arcadis GreenSpark Patrick O'Malley Supervisor 7 Craig Collins O'Connor Foreman Rigoberto Araiza Carrasco I-Build Laborer Trevor McCurry I-Build Foreman Bruce Hutchinson O'Connor Operator 7 **Bob Cutter** O'Connor Mechanic/Driver 2

DAILY INSPECTION REPORT Fort Edward Landfill (Site # 558001)

Y INSPECTION dward Landfill (S	_							Date: (Page 2)2/06/2
Equipment Descript	ion		Cont	ractor/Vendor		(Quantity	Use	ed
Ford F-150 P/U			G	reenSpark			1	Y	,
Ford F-250 P/U				I-Build			1	Y	•
Gehl VT320 Skid-Ste	Gehl VT320 Skid-Steer			reenSpark			1	Υ	
Hitachi ZX135US Exca		O'Connor				1	<u>Y</u>		
Dodge Ram 3500 P/U w/S Dodge Ram 1500 P/		O'Connor O'Connor				1			
Bouge Ham 1000 17				O COMING			1 Y		
Material Description	Imported/ Exported Waste Profile Source or Disposal Profile Source or Disposal Profile Source or Disposal Profile Prof			Daily	Daily Weight				
	to Site	off Site	(If	Applicable)	Facility ((If Ap	plicable)	Loads	(tons)*
On-Site scale for off-site ship	ment delivery	ticket for mater	ial receiv	red					
/isitors to Site Name			Po	oroconting		En	torod Eva	:lusion/CR	7 7ono
Name	Name					Yes		No 🗆	
						Yes		No □	
								No 🗆	
						Yes		NO ⊔	
ite Representatives									
	Name				Rep	orese	enting		
Mik	e Merwin			Arcadis					
roject Schedule Com	ments								
Vork projected to resun		of Monday,	Februa	ary 20, 2023, t	o initiate tes	st pit	work.		
ssues Pending									
nteraction with Public	, Property (Owners, Me	edia, et	c.					
None.									



Site Photographs (Descriptions Below)



O'Connor crew rigging basket for removal.



Basket removed from area shown in photo #1.



Row of baskets to be removed from swale.



Baskets removed and staged on landfill cap.



View of swale following removal of baskets.



Solar panel module box secured with ratchet strap.

Comments

DAILY INSPECTION REPORT Page 4 of 6 Fort Edward Landfill (Site # 558001) Date: 02/06/2023

Site Inspector(s): Mike Merwin	Date: 02/06/2023

Videos of discreet operations have been provided to the DEC Project Manager to facilitate understanding of the ongoing work? Yes \square No \boxtimes

DAILY HEALTH CHECKLIST

Is social distancing being practiced?	Yes ⊠	No □
Is the tail gate safety meeting held outdoors?	Yes ⊠	No □
Are remote/call in job meetings being held in lieu of meeting in person where possible?	Yes ⊠	No □
Were personal protective gloves, masks, and eye protection being used?	Yes □	No ⊠
Are sanitizing wipes, wash stations or spray available?	Yes ⊠	No □
Have any workers/visitors been excluded based on close contact with individuals diagnosed with COVID-19, have recently traveled to restricted areas or countries, or are symptomatic (fever, chills, cough/shortness of breath)?	Yes □	No ⊠
Comments: None		

REMEDIAL ACTIVITIES AT PROPERTIES

1.	Have anyone at this location been tested and confirmed to have COVID-19?	Yes □	No ⊠
2.	Is anyone at this location isolated or quarantined for COVID-19?	Yes □	No ⊠
3.	Has anyone at this location had contact with anyone known to have COVID-19 in the past 14 days?	Yes □	No ⊠
4.	Does anyone at this location have any symptoms of a respiratory infection (e.g., cough, sore throat, fever, or shortness of breath)?	Yes □	No ⊠
5.	Does the Department and its contractors have your permission to enter the property at this time?	Yes ⊠	No □
If Yes to	If it is <u>not</u> critical that service/entry be carried out immediately and can be postponed until the risk of COVID-19 is lower, or can be accomplished remotely/without entry, postpone or conduct service without entry. If it is critical that service/entry be carried out immediately, advise occupants that as a precaution and for our own protection, project personnel will be donning appropriate PPE* (including respiratory protection) - and do so prior to entry.	Yes □	No ⊠
Commo None	<u>ents:</u>		

On-Site Waste Storage



DAILY INSPECTION REPORT Fort Edward Landfill (Site # 558001)

	,		,
Drums, roll offs and piles are staged in secure areas?	Yes □	No □	N/A⊠
Liners and berms have been installed if necessary to prevent cross contamination of clean areas?	Yes □	No □	N/A⊠
Containers are in good condition or properly overpacked?	Yes □	No □	N/A⊠
Waste materials are scheduled to be properly characterized and disposed of prior to demobilization?	Yes □	No □	N/A⊠
Complying with RCRA 90 day storage limitation for hazardous waste?	Yes □	No □	N/A⊠
Piles are securely covered when not in use?	Yes □	No □	N/A⊠
Containers are closed when not in use?	Yes □	No □	N/A⊠
Staging areas should be inspected periodically and any issues addressed immediately?	Yes □	No □	N/A⊠
Signage and labeling comply with RCRA requirements for all staging areas and containers?	Yes □	No □	N/A⊠
If any issues noted, has Contractor been notified?	Yes □	No □	N/A⊠
No waste generated during site activities.			

Page **5** of **6 Date: 02/06/2023**

NUISANCE CHECKLIST

Were there any community complaints related to work on this date?	Yes □	No ⊠	N/A□
Were there any odors detected on this date?	Yes □	No ⊠	N/A□
Was noise outside specification and/or above background on this date?	Yes □	No ⊠	N/A□
Were vibration readings outside specification and/or above background on this date?	Yes □	No □	N/A⊠
Any visible dust observed beyond the work perimeter on this date?	Yes □	No ⊠	N/A□
Any visible contrast (turbidity) beyond engineering controls observed on this date?	Yes □	No ⊠	N/A□
Was turbidity checked at the outfall(s)?	AM □	РМ□	N/A⊠
Were any property owners NOT provided advance notice for work performed on this property on this date?	Yes □	No □	N/A⊠
Was the temporary fabric structure closed at the end of the day?	Yes □	No □	N/A⊠
Has Contractor failed to protect all foundations and structures adjacent to and adjoining the site which are affected by the excavations or other operations connected with performance of the Work?	Yes □	No □	N/A⊠
If yes, has Contractor been notified?	Yes □	No □	N/A⊠
Comments:			

RESILIENCE/GREEN REMEDIATION CHECKLIST



DAILY INSPECTION REPORT Fort Edward Landfill (Site # 558001)

Is site power procured from renewable energy sources (e.g., solar, wind, geothermal, biomass Yes □ No □ N/A⊠ and biogas)? Is the Contractor employing 2007 or newer or retrofitted (BART*) diesel on-road trucks and non- $N/A \boxtimes$ Yes □ No □ road equipment? N/A⊠ Is vehicle idling adequately reduced per 6NYCRR Part 217-3? Yes □ No □ Have equipment operators been trained in the idling requirements of 6NYCRR Part 217-3? Yes □ No □ N/A⊠ N/A⊠ Is BART-equipped equipment properly maintained and working? Yes □ No □ Is work being sequenced to avoid double handling? Yes ⊠ No □ N/A□ Is there an onsite recycling program for CONTRACTOR-generated wastes and is it complied Yes □ No □ N/A⊠ with? Are office trailer heating and cooling systems maintained at efficient set points, have N/A⊠ Yes □ No □ programable thermostats been installed? Are products and materials used in performance of the work appropriately certified (e.g., LEED, N/A⊠ Yes □ No □ Energy Star, Sustainable Forestry Initiative®, etc.)? Are resiliency features included in the design, or completed remedy properly installed and/or N/A⊠ Yes □ No □ maintained (flood control, storm water controls, erosion measures, etc.)? Are green remediation elements included in the design, or completed remedy properly installed and/or maintained (e.g., porous pavement, geothermal, variable speed drives, native plantings, Yes □ No □ N/A⊠ natural stream bank restoration, etc.)? Has Contractor been notified of any deficiencies? N/A⊠ Yes □ No □ Comments: None

Page 6 of 6

Date: 02/06/2023

^{*} BART - Best Available Retrofit Technology

