NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Division of Environmental Remediation

Inactive Hazardous Waste Site Operations and Maintenance Review Report

)	Form Date 96.10.01
Site Name: Rose Valley Land	1: Class: 2 Number: 6-22-017
O&M Funding Source: □ State Superfund □	Federal Superfund Municipal Responsible Party
O&M Information: O&M Start: 10/13/91	Z_ End: ← Annual Cost: \$30₺@ Estimated
Interim Remedial Measures/Operable Units in O&M PI Drum Removal Cap/Cover Groundwater Recovery/Treatment Air Sparging/Stripper System TSupply/System	hase: Soil Removal Containment Structure Leachate Collection/Treatment Creatment/Filtration Plant/System Tank Removal Fence/Security Vapor Extraction/Treatment Potable Water
Institutional Controls: Deed Restriction Sampling Other: None	□ Discharge Permit □ Department of Health
O&M Review Information: Reports: Semi annual by Inspection: Sampling: Ander WA DOD 38 Other:	Consultant, Earth Tech. Inc
Conclusions:	
Remedy Effective?	
ROD Compliance?	
Consent Order Compliance? Yes No:	
Other:	
Recommendations:	
ROD/Consent Order Modifications?	rabove) Reclassify the Site? □ No □ Yes → Class:
Comments:	
Continues to function well vendring site related Contominants for well writed.	
Project Manager: 10/rv/99 Thomas Vickleson 10/rv/99 Date	Reviewer: Signature Date
Thomas Vickerson BCS 7-7878	
Name Region or Bureau Telephone	Name Region or Bureau Telephone