(315) 437-2533 (315) 437-1775 www.rustonpaving.com

June 25, 2015

Metalico Aluminum Recovery, Inc. C/O: Ginny Hopkins 6223 Thompson Road Syracuse, New York 13206

Dear Mr. Flanagan:

Re: CAMU Cover Repairs

I have completed the inspection of the asphalt cover on the CAMU area. I have found a few areas where the existing asphalt patches and concrete pads needed to be crack sealed again. There were some additional areas within the cover area that required crack sealing along with a few spots of vegetation growing on the edge of the asphalt slope. The vegetation along the slopes of the pavement have been removed and are not entering the CAMU cap area. I have included (6) photos of the work areas showing the repairs.

## Repair Procedures:

Crack seal edges and existing asphalt patches. Remove vegetation Power sweep entire pad

All repairs were completed by June 25, 2015.

Should you have any questions or concerns, please contact me at (315) 437-2533.

Sincerely,

Ruston Paving Co., Inc.

Obistol & Lewin

Chris Laurin Project Manager







