

NEW YORK
state department of
HEALTH

Howard A. Zucker, M.D., J.D.
Acting Commissioner of Health

Sue Kelly
Executive Deputy Commissioner

August 20, 2014


Mr. Payson Long
NYS Dept. of Environmental Conservation
Div. of Environmental Remediation, Remedial Bureau E
625 Broadway Street
Albany, NY 12233 – 7017

Re: **2013 Annual Report**
Pollution Abatement Services-Main Site
Site# 738001
Oswego, Oswego County

Dear Mr. Long:

I reviewed the 2013 Annual Report received on August 4th 2014 for the Pollution Abatement Services-Main Site in Oswego, Oswego County. The report is a compilation of four Quarterly Progress Reports of the required monitoring under the Site Management Plan (SMP) or its equivalent. The Site Management Plan or equivalent includes monitoring to ensure that the engineering controls are functioning as designed. According to the 2013 Annual Report, site maintenance activities included perimeter fence repairs, inspection of the leachate discharge pumping system and inspection of the Site cap. Based on this review, it appears remaining contamination is being properly managed and remains protective of human health. If you have questions or wish to discuss the site further, please call me at (518) 402-7860

Sincerely,



Ian Ushe, Public Health Engineer I
Bureau of Environmental Exposure Investigation

ec: M. Schuck / e-File
J. Strepelis –NYSDOH CRO
N. Roy – OCHD
M. Cruden / S. Edwards – NYSDEC Central Office
H. Warner – NYSDEC Region 7
P:\Bureau\Sites\Region_7\Oswego\738001\2013 Annual Report.pdf