

FACT SHEET



# Additional Environmental Investigations Planned at Erdle Perforating

In October 1994, Erdle Perforating signed a legal agreement with the New York State Department of Environmental Conservation (DEC) to perform an environmental investigation at the Erdle Perforating site located at 100 Pixley Industrial Parkway in the Town of Gates, Monroe County (see Figure). The Department of Environmental Conservation is providing this fact sheet to explain highlights of the planned investigation and how to get more information.

## About the Erdle Perforating Site:

Erdle Perforating manufactures perforated sheet metal products. Trichloroethene, a common degreaser also known as TCE, was used during Erdle's manufacturing process to remove perforating oils. Perforating oils and trichloroethene waste stored three were in separate underground storage tanks. In February 1987, water was discovered in the trichloroethene waste tank and the tank was taken out of service. Subsequent groundwater and soil sampling near the underground tanks revealed the presence of trichloroethene and other related compounds. As a result, two tanks and approximately 100 cubic yards of soil immediately surrounding the tanks were removed and disposed of off-site in July of 1987. Erdle also removed the third underground storage tank to discontinue the practice of underground storage. Erdle has since discontinued use of the degreasing operation.

In addition to the investigations performed, a cleanup technology has been implemented at the site. This technology involves extracting and treating both air and groundwater from the subsurface. This cleanup has focused on the area around and down-gradient of the former underground storage tanks. The cleanup began in 1996. Additional information on this cleanup is available for review at the locations listed below.

#### Investigation Results To Date:

Investigations began in late 1994 and have proceeded in several phases. Investigations have revealed the presence of trichloroethene and related compounds in soil and groundwater beneath the site. In 1999, four groundwater monitoring wells were installed off-site, along the railroad tracks. These wells had detections of site-related compounds.

### **Upcoming Investigation:**

Erdle Perforating has submitted a work plan for additional investigations. This work plan is dated October 26, 2000 and is available for review at the locations listed below. Investigations planned include additional soil sampling in the bedding of sewer lines crossing the site; installing temporary borings to obtain soil and groundwater samples; and, installing additional groundwater monitoring wells off-site to help define the extent of groundwater contamination. The investigations are scheduled to begin in November, 2000 and last approximately one month.

#### What Happens Next:

After the investigation is complete, Erdle Perforating will submit a report to DEC. The DEC will evaluate the report and determine if additional investigation or cleanup action is necessary. Following completion of the investigations, Erdle Perforating will prepare a feasibility study which will outline potential final remedies for the site.

#### For More Information:

Documents related to this investigation are available for you to review at:

Gates Public Library 1605 Buffalo Road Rochester, NY 14624-1695 (716) 247 - 6446 Hrs: M-F 10:00am - 9:00pm Sat 10:00am - 5:00pm

or

NYS Department of Environmental Conservation Region 8 Office 6274 E. Avon-Lima Rd. Avon, NY 14414 Hours: Monday- Friday 8:30 - 4:45 (716) 226-5355 (Contact David G. Pratt, P.E. for an appointment)

We encourage you to contact the representatives listed below with questions, comments or concerns. If you know someone who would like to be added to the mailing list, have them send in the attached mailer or contact one of the people listed below. You do **not** have to return the mailer if you received this fact sheet in the mail; your name will automatically remain on the mailing list.

# For Question About the Investigation, Contact: David G. Pratt, P.E., Project Manager Linda Vera, Citizen Participation Office 226-5324 NYS Department of Environmental Conservation 6274 East Avon-Lima Road Avon, NY 14414

#### > For Site-Related Health Questions, Contact:

Fay Navratil NYS Department of Health 547 River Street Troy, NY 12180 (800)458-1158 ext. 27860 or Mark VanDeusen (800)458-1158 ext 27530 Joseph Albert Monroe County Health Department 111 Westfall Road - PO Box 92832 Rochester NY 14692 (716) 274-6904

Site Map




FIGURE 1 SITE LOCATION - ERDLE PERFORATING

# **NYSDEC Mailer**

Please feel free to use this mailer for any of the following purposes:

- 1. You would like to be placed on our Erdle Perforating mailing list.
- 2. You would like to include the name and address of someone you know who maybe interested in receiving future fact sheets.
- 3. You would like to be taken off our Erdle Perforating mailing list.
- 4. You would like to provide us with a change of name or address.
- 5. You would like to provide us with a comment or concern.

FOLD		
Please complete the form as indicated below, fold and mail directly to the DEC.		
Add the following name(s):		
	_	
Delete the following name(s):	-	
	-	
Make the following changes:	_	
(Old)		(New)
	-	
	FOLD	
Comments or Concerns:		

Linda Vera New York State Department of Environmental Conservation 6274 East Avon-Lima Rd Avon, NY 14414-9519