New York State - Department of Environmental Conservation Division of Environmental Remediation <u>Periodic Review Evaluation Report</u>

Period covered by -- 2007-08

Site Code: 932020 Site Nat	me: Love Canal Class: 04
Program Lead: State Superfund Program Site Ma	nagement Funding Source: Federal Government (EPA)
Start Date: 12/01/1979 ACT	
IC/EC Certification: Recieved Date:	Accept Date:
DEC Inspection Date: 03/24/2008 Last Date of DEC Insp	pection
Report Used for Evaluation: Site Management, Longterm Monitori	ng, Discharge Monitoring, Inspection
ROD Complicance? Yes	
Long Term Monitoring (effectiveness of remedy): Yes	Frequency:
Treatment System (Monitoring performance of remedy): Yes	Frequency: Number of Wells: 38
Problem Status:	
Reporting / Monitoring / ICs Slight	
Elements	
Detection Limits	
Monitoring Data	
gradients. Leachate continues to be treated through clarification, bag fil uniformity. The PLC system is reilable and stable. GW samples are gra 2007. Results were ND for VOC's and SVOC's and very low J values in	I data indicates that the collection system is maintaining inward groundwater tration and carbon adsorption. Plant and field pumps have been replaced for abbed annually to monitor quality. The Department split at 5 wells in July a 4-6 pesticide compounds. The cap is in good condition. There were no good condition. The site is fenced and well maintained. A five year review in the process of being updated.
Contaminent of concern OU	Media/Receptor
BENZOYL CHLORIDE, METAL CHLORIDES 01	
LIQUID DISULFIDES, CHLOROBENZENES, CHLOROTOLOTE	NE
BENZYL CHLORIDE, THIONYL CHLORIDE, 01	
SULFIDES, MISC. ACID CHLORIDES, 01	
HEXACHLORHEXANES, TRICHLOROPHENOL, 01	
DODECYL MERCAPTAINS 01	
Next Review:	Priority: 01
Project Manager: bpsadows	Reviewer: GPSUTTON
Signature: Date:	Signature: Date: 03/31/2008
Name Region or Bureau Telepho	ne Name Region or Bureau Telephone

New York State - Department of Environmental Conservation Division of Environmental Remediation Periodic Review Evaluation Report

Remedies	OU	Site of Treatment	Date in Place	Remedy Effective
6 NYCRR Part 360 Cap	01	XX		Ongoing
Hydraulic Control	01	XX		Ongoing
DNAPL Recovery - Mechanical	01	XX		Ongoing
Granular Activated Carbon	01	XX		Ongoing
Leachate Recovery	01	XX		Ongoing
Excavation (removal offsite)	14	XX		Ongoing
Plume Management Monitoring	14	XX		Ongoing

Next Review:			Priority: 01			
Project Manager:	bpsadows		Reviewer:	GPSUTTON		
Signature:	Date:		Signature:		Date:	03/31/2008
Name	Region or Bureau	Telephone	Name		Region or Bureau	Telephone