## **New York State - Department of Environmental Conservation Division of Environmental Remediation Periodic Review Evaluation Report**

## Period covered by -- 2008-09

Site Code:

932020

Site Code: 932	020	Site Name:	Love Canal	Class:	04
Program Lead:	State Superfund Program	Site Manage	ement Funding Source:	Federal Government (EPA)	
Start Date: 12/	01/1979 ACT				
IC/EC Certification	n: Recieved Date:	A	Accept Date:		
<b>DEC Inspection Da</b>	te: 06/24/2008 Last Date	of DEC Inspecti	ion		
Report Used for Ev	valuation: Site Management, Longte	rm Monitoring, 1	Discharge Monitoring, Ins	spection	
ROD Complicance	? Yes				
Long Term Monito	oring (effectiveness of remedy):	Yes Fr	equency:		
Treatment System	(Monitoring performance of remedy)	: Yes Fr	equency:	Number of Wells:	31
Problem Status:					
OM&M Plan. All c collection system is adsorption. Approx system is reliable ar ND. The cap was fo	110	on and effective.  ents. Leachate co 008 of which ~30  oles in June 2008  ns of erosion. Pe	A review of the hydraulication of the hydraulication of the continues to be treated through 00K was pumped from the continues. Previous J value pesticiterimeter fencing and gates	ic control data figures for 2008 indicating the clarification, bag filtration, and ce a 102nd St. site. The Process Logic Ce de hits were fewer at very low concert	ates that the arbon Control atrations or
Contaminent of	concern	OU	Media/Receptor		
BENZOYL CH	ILORIDE, METAL CHLORIDES	01			
LIQUID DISU	LFIDES, CHLOROBENZENES, CHLO	OROTOL <b>OJE</b> NE			
BENZYL CHL	ORIDE, THIONYL CHLORIDE,	01			
	ISC. ACID CHLORIDES,	01			
	HEXANES, TRICHLOROPHENOL,	01			
Evaluation: The	Remedy is performing properly and is	effective.			
Next Review:			Priority: 01		
Project Manager:	bpsadows		Reviewer: GPSUT	TON	
Signature:	Date:		Signature:	Date: 03/20	/2009
Name	Region or Bureau	Telephone	Name	Region or Bureau	Telephone
			•		

04

## New York State - Department of Environmental Conservation Division of Environmental Remediation Periodic Review Evaluation Report

Remedies	OU	Site of Treatment	Date in Place	Remedy Effective	
6 NYCRR Part 360 Cap	01	XX		Ongoing	
Hydraulic Control	01	XX		Ongoing	
DNAPL Recovery - Mechanical	01	XX		Ongoing	
Granular Activated Carbon	01	XX		Ongoing	
Leachate Recovery	01	XX		Ongoing	
Excavation (removal offsite)	14	XX		Ongoing	
Plume Management Monitoring	14	XX		Ongoing	

Next Review:			Priority: 01			
Project Manager:	bpsadows		Reviewer:	GPSUTTON		
Signature:	Date:		Signature:		Date:	03/20/2009
Name	Region or Bureau	Telephone	Name		Region or Bureau	Telephone