



Department of
Environmental
Conservation

Division of Environmental Remediation
Central Office

DAILY INSPECTION REPORT

Site Code #: B-00-184	Date: 12/29/2015	Report #: 10
------------------------------	-------------------------	---------------------

Site Name: Fosters Refrigeration
Location: City of Hudson, Columbia Co.
DEC Proj. Mgr.: Michael Mason
Contractor: Precision Environmental
Contractor Proj. Mgr.: Steve Phelps

	AM	PM
Weather	Sleet	Light Rain
Temperature	32	40
Wind Direction	North	North

Description of work performed by contractor this report period:

Precision Environmental:

- A skid steer with a Geoprobe attachment was used to collect soil samples at the north end of the site. Borings were performed at 12 locations with samples collected at 0-3ft, 4-6ft, 7-9ft and 10-12ft. Samples were sent to Test America Labs to be analyzed for metals and PCBs

Discussions/comments regarding visitors, contractor and/or engineer:

- Ash backfill was encountered in cores at depths of 0 to 6ft

Change Orders:

Sampling and Analyses:

Major Issues	Description & Reason

Health & Safety:

Level of protection: D

Is the level of protection in conformance with the approved Health & Safety Plan? Yes

List deviations: None

Are atmospheric monitoring results acceptable? NA

Site Visitors	Representing	Entered Exclusion Zone

Contractor's Information:

Contractor Hours 7:00am – 3:30pm

Subcontractor	Activity	Hours Worked

Equipment	P	1	2	3	4	Personnel	P	1	2	3	4
Skid Steer/Geoprobe	1					Operator	1				
Utility Truck/E350	1					Geologist	1				
Equip Trailer	1										

Site Representative: Kristopher Keenan

Date: 12/29/2015

Representative's Signature:



Photo Log



Collecting samples



Ash backfill encountered in 0-6ft samples



Flags used to mark boring locations

Site Map

