



Daily Activity Report

Seton Brilla Charter School
1956 Jerome Avenue, Bronx, NY
BCP No. C203152

General Site Information

Date:	Thursday, March 2, 2023
Weather:	Rain, 38-56°F
Wind Direction/Speed:	NE @ 3 mph
AKRF Personnel on Site:	Marcela Sanchez
AKRF Equipment on Site:	Mini RAE 3000 Photoionization Detector [(PID) x1], 2 Fixed Air Monitoring Stations [DustTrak
Visitors:	None.

Contractor Information

Contracting Company	Main Personnel	Equipment
Casino Construction	Connor McGrory	Excavator, CFA Drill Rig

Description and Location of Work Activities Performed

1) Soi/fill from grid WC-02 was excavated and sent for off-site disposal at the Clean Earth - Bethlehem, PA facility.
 2) Endpoint sample SW-11C_8-10_20230302 was collected from the north sidewall of the groundwater treatment area. The sample was submitted for laboratory analysis of petroleum VOCs.
 3) One truckload of 3/4 inch virgin bluestone from the Braen Stone Sparta Quarry was imported to the site as backfill for the groundwater treatment area excavation, and for use along the site boundary in WC-03.

Site Soil Disposal Tracking Information

Destination Facility	Daily Trucks	Total Trucks	Daily Approx. Cubic Yds	Total Approx. Cubic Yds	Total Site Loads	Total Approximate Cubic Yards
Clean Earth Carteret	0	73	0	1,460	166	3,320
Clean Earth Southeastern Pennsylvania	1	67	20	1,340		
Concrete Disposal	0	26	0	520		
N/A	0	0	0	0		
N/A	0	0	0	0		

CAMP Air Monitoring Results


CAMP Station	UPWIND				DOWNWIND		
Odors:	None.				None.		
VOC Action Level Exceedance(s):	NA				NA		
Particulate Action Level Exceedance(s):	NA				NA		
Maximum VOC Level (15 min ppm):	NA				NA		
Maximum Particulate Level (15 min mg/m ³):	NA				NA		

Notes: CAMP and roving air monitoring were not performed due to inclement weather.

Additional Information

Planned Work Activity for Following Day/Week:	1) Excavation of soil/fill to uncover piles. 2) Cutting piles to final elevations
Comments:	None.

Site Map



LEGEND

- PROJECT SITE BOUNDARY
- LOT BOUNDARY AND TAX LOT NUMBER
- 2853** BLOCK NUMBER
- REMEDIAL EXCAVATION TO APPROXIMATELY TWO FEET BELOW EXISTING GRADE
- REMEDIAL EXCAVATION TO GROUNDWATER (SOURCE AREA)

- CONFIRMATION DOCUMENTATION BOTTOM SAMPLE
- SOURCE AREA DOCUMENTATION BOTTOM SAMPLE
- DOCUMENTATION SIDEWALL SAMPLE

NOTE

REMEDIAL EXCAVATION WILL INCLUDE REMOVAL OF APPROXIMATELY 1,280 TONS (850 CUBIC YARDS) OF SOURCE MATERIAL ASSOCIATED WITH NYSDEC SPILL NO. 2103719 AND APPROXIMATELY 860 TONS (570 CUBIC YARDS) OF SOIL/FILL FROM THE UPPER 2 FEET SITE-WIDE.



Map Source:
NYCDCP (NYC Dept. of City Planning) GIS database

© 2021 AKRF. W:\Projects\210024 - 1566 JEROME AVENUE\Technical\GIS and Graphics\SR\RAW\Fig210024_Figure 9 Proposed Remedial Excavation and Documentation Sample Location Plan.mxd 10/25/2021 2:05:38 PM iszslus



440 Park Avenue South, New York, NY 10016

1956 Jerome Avenue
Bronx, New York

**TRACK 4 CLEANUP AND DOCUMENTATION
SAMPLE LOCATION PLAN**

DATE	04/29/2022
PROJECT NO.	210024
FIGURE	11

Site Photographs

Photograph 1 -
Excavation in Grid
WC-02 for endpoint
sampling, view facing
south.



Photograph 2- The
excavator spreading
3/4-inch virgin
bluestone in WC-02,
view facing
southwest.



Photograph 3-
Excavation of soil
against SOE wall in
WC-03, view facing
south.

