APPENDIX H

NYSDEC Spill Reports

//	NYSDEC SPILL RE			
		SPILL NUMBER 9604977		
PILL NAME: CON ED FUEL DEPO				
CALLER'S NAME: LISA PRIMEGGIA		OTIFIER'S NAME: _		
CALLER'S AGENCY: CON ED		OTIFIER'S AGENCY:		
CALLER'S PHONE: (212) 580-6763	EXT No	OTIFIER'S PHONE:	(212) 580-6763	EXT
SPILL DATE: 07/15/1996	TIME:09:0	0		
CALL RECEIVED DATE: 07/17/1996	TIME:10:20	RECEIVED B	Y CID #: 257	
Material Spilled	Mat. Class	Am't Spilled	Units	Am't Recovered
1) PCB OIL	(Pet)Haz-Other-U	nk. Unknown	(Gal) Lbs	Unknown
2) LEAD			(Gal) Lbs	Unknown
3) TOLUENE	Pet-Haz-Other-U	nk. Unknown	(Gal) Lbs	Unknown
4)		nk	Gal - Lbs	
SPILL LOCATION			NTIAL SPILLER	
PLACE: CON ED FUEL DEPOT	. N	AME: PAINT F		
		TREET: UNKNOW	N	
STREET: 214 KENT AVE				
T/C/V: BROOKLYN CO:	KINGS S	TATE:	ZIP	•
CONTACT: LISA PRIMEGGIA	C	ONTACT:		
PHONE: (212) 580-6763	EXT PI	HONE:		EXT
SPILL CAUSE		SP	ILL SOURCE	
Human Error Tank Test Failure *	Tank Failure	Gas Station	Private Dwelling	Non-Maj Facility
Traffic Accident Housekeeping	Tank Overfill	Passenger Vehicle		(Comm/Indust) Non-Comm/Instit
Equipment Failure Deliberate Vandalism Abandoned Drums	Other (Unknown)	Comm. Vehicle Tank Truck	Railroad Car Major Facility	Unknown
			ILL REPORTED B	
(On Land) RESOURCE AFFECTED Groundwater	<u>)</u> Air	Responsible Party	Tank Tester	Local Agency
In Sewer Surface Water **	All	(Affected Persons)	DEC	Federal Gov't
		Police Department	Citizen	Other
**WATERBODY:		Fire Department	Health Dept.	
CALLER REMARKS: soil samples		above were in the	e sample calle:	r beliaves it is
coming from the paint factory	next door			
*PBS Number Tank Numb	er Tank Size	Test M	lethod	Leak Rate
PRIMARY CONTACT CALLED DATE:	TIME:	hrs. REACHED DATE	:	TIME: hrs
SECONDARY CONT. CALLED DATE:		_hrs. FAXED BY CID#		
PIN# T&A	Cost Center	IS	R to Central Office	
Cleanup Ceased		Last Inspection		Penalty NO

INVES-COM

Resp. Party 1 2 3 4 5 6

Is Updated? NO

Created on 07/17/1996 **Date Printed:** 10/06/2000

UST Trust Eligible NO

ENF-INIT

Site: A B OD E

Last Updated on 08/27/1996

RP-CUI

DATA INPUT []

CAP

Reg Close Date

EDO



Spill Incidents Database Search Details

Spill Record

Administrative Information

DEC Region: 2

Spill Number: 9815508 **Spill Date/Time**

Spill Date: 03/30/1999 **Spill Time:** 12:00:00 PM

Call Received Date: 03/30/1999 Call Received Time: 12:55:00 PM

Location

Spill Name: FYN PAINT

Address: 33 NORTH 1ST STREET City: BROOKLYN County: Kings

Spill Description

Material Spilled Amount Spilled Resource Affected

SOLVENTS UNKNOWN Soil PAINT THINNERS UNKNOWN Soil

Cause: Tank Failure

Source: Commercial/Industrial

Waterbody:

Record Close

Date Spill Closed: 05/23/2000

"Date Spill Closed" means the date the spill case was closed by the case manager in the Department of Environmental Conservation (the Department). The spill case was closed because either; a) the records and data submitted indicate that the necessary cleanup and removal actions have been completed and no further remedial activities are necessary, or b) the case was closed for administrative reasons (e.g., multiple reports of a single spill consolidated into a single spill number). The Department however reserves the right to require additional remedial work in relation to the spill, if in the future it determines that further action is necessary.

If you have questions about this reported incident, please contact the Regional Office where the incident occurred.

Refine Current Search