

Enclosure 2 NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION Site Management Periodic Review Report Notice Institutional and Engineering Controls Certification Form



Sit	e No.	C224207	Site Details		Box 1	
		rmer Sunbelt Equipmer	nt			
Site City Co		25 KENT AVENUE ooklyn	Zip Code: 11249			
Re	porting Perio	od: April 27, 2019 to Apri	il 27, 2022			
					YES	NO
1.	Is the inform	mation above correct?			X	
	If NO, inclu	ide handwritten above or	on a separate sheet.			
2.		or all of the site property nendment during this Rep	been sold, subdivided, merge porting Period?	ed, or undergone a		X
3.		been any change of use a RR 375-1.11(d))?	at the site during this Reportir	ng Period		X
4.		ederal, state, and/or loca e property during this Rep	l permits (e.g., building, disch porting Period?	narge) been issued	X	
			s 2 thru 4, include documen viously submitted with this			
5.	Is the site of	currently undergoing deve	elopment?			X
					Box 2	
					YES	NO
6.	Is the curre	ent site use consistent wit	th the use(s) listed below?		X	
7.	Are all ICs	in place and functioning	as designed?	X		
	IF TH		QUESTION 6 OR 7 IS NO, sig IE REST OF THIS FORM. Oth	-	ind	
AC	Corrective M	easures Work Plan mus	t be submitted along with thi	s form to address th	nese iss	ues.
Sig	nature of Ow	vner, Remedial Party or De	esignated Representative	Date		

		Box 2	A
	Has any new information revealed that assumptions made in the Qualitative Exposure	YES	NO
0.	Assessment regarding offsite contamination are no longer valid?		X
	If you answered YES to question 8, include documentation or evidence that documentation has been previously submitted with this certification form.		
9.	Are the assumptions in the Qualitative Exposure Assessment still valid? (The Qualitative Exposure Assessment must be certified every five years)	X	
	If you answered NO to question 9, the Periodic Review Report must include an updated Qualitative Exposure Assessment based on the new assumptions.		
SIT	E NO. C224207	Bo	x 3
	Description of Institutional Controls		
Parce	<u>el Owner</u> Institutional Contr	ol	
3022	320001 19 Kent Acquisition LLC		
	Ground Water Us		tion
	Landuse Restricti Site Management	-	
	asement and Site management Plan are in place for two 900 square foot areas of the site		1
allow	restricted residential use, and the other will allow commercial use. Both will have ground ctions.		
		Bo	x 4
	Description of Engineering Controls		
No	one Required		
Nc	t Applicable/No EC's		

	Box 5
Periodic Review Report (PRR) Certification Statements	
I certify by checking "YES" below that:	
 a) the Periodic Review report and all attachments were prepared under the direction or reviewed by, the party making the Engineering Control certification; 	f, and
b) to the best of my knowledge and belief, the work and conclusions described in this are in accordance with the requirements of the site remedial program, and generally and program and the information program to the information program.	
engineering practices; and the information presented is accurate and compete. YES	NO
$ar{\mathbf{X}}$	
For each Engineering control listed in Box 4, I certify by checking "YES" below that all of the following statements are true:	
(a) The Engineering Control(s) employed at this site is unchanged since the date that the Control was put in-place, or was last approved by the Departme	ent;
(b) nothing has occurred that would impair the ability of such Control, to protect public the environment;	health ar
(c) access to the site will continue to be provided to the Department, to evaluate the remedy, including access to evaluate the continued maintenance of this Control;	
(d) nothing has occurred that would constitute a violation or failure to comply with the Site Management Plan for this Control; and	
(e) if a financial assurance mechanism is required by the oversight document for the s mechanism remains valid and sufficient for its intended purpose established in the doc	
YES	NO
$\mathbf{\bar{X}}$	
IF THE ANSWER TO QUESTION 2 IS NO, sign and date below and DO NOT COMPLETE THE REST OF THIS FORM. Otherwise continue.	
A Corrective Measures Work Plan must be submitted along with this form to address these is	ssues.
Signature of Owner, Remedial Party or Designated Representative Date	

Γ

IC CERTIFICATIONS SITE NO. C224207	
	Box 6
SITE OWNER OR DESIGNATED REPRESENTATIVE SIGNAT I certify that all information and statements in Boxes 1,2, and 3 are true. I unders statement made herein is punishable as a Class "A" misdemeanor, pursuant to S Penal Law.	stand that a false
I <u>Rick Furches</u> at <u>2929 Arch Street, 28th fl</u> print name print business address	<u>Philadelphia P</u> A 19104
am certifying as (Ow	vner or Remedial Party)
for the Site named in the Site Details Section of this form.	4, 2022
Signature of Owner, Remedial Party, or Designated Representative Date Rendering Certification	te

FORMER SUNBELT EQUIPMENT

25 KENT AVENUE, BROOKLYN, NEW YORK 11249

PERIODIC REVIEW REPORT


NYSDEC BCP Number: C224207

Submitted to:



New York State Department of Environmental Conservation **Division of Environmental Remediation, Region 2** 47-40 21st Street Long Island City, NY 11101-5407

Prepared by:



AMC Engineering PLLC Astoria, NY 11105

REPORTING PERIOD:

APRIL 27, 2019 to April 27, 2022

TABLE OF CONTENTS PERIODIC REVIEW REPORT (APRIL 27, 2019 to April 27, 2022) FORMER SUNBELT EQUIPMENT 25 KENT AVENUE, BROOKLYN, NEW YORK 11249

I. EXE	CUTIV	E SUMMARY	1
П.	SITE	OVERVIEW	2
	Α.	Site Location	2
	В.	Site Chronology	2
III.	REIV	EDY PERFORMANCE, EFFECTIVENESS & PROTECTIVENESS	3
IV.	IC P	AN COMPLIANCE REPORT	4
	A1.	IC Requirements and Compliance	4
		1. IC Controls	4
		2. Status of each IC	5
		3. Corrective Measures	
		4. IC Conclusions and Recommendations	5
	A2.	EC Requirements and Compliance	6
		1. EC Controls	6
		2. Status of each EC	6
		3. Corrective Measures	6
		4. EC Conclusions and Recommendations	
	В.	IC Certification	
۷.	MAI	NTENANCE AND INSPECTION PLAN COMPLIANCE REPORT	8
	Α.	Components of the Maintenance and Inspection Plan	8
		1. Composite Cover Inspection	8
		2. Reporting	
	В.	Summary of the Composite Cover Inspection Completed During Reporting Period	9
		1. Composite Cover System	9
	С.	Evaluation of Remedial Systems	9
		1. Composite Cover System	9
	D.	Composite Cover Deficiencies	
	Ε.	Conclusions and Recommendations for Improvements	9
VI.	OVE	RALL PRR CONCLUSIONS AND RECOMMENDATIONS	10
	Α.	Compliance with SMP	10
	В.	Future PRR Submittals	10

FIGURES

Figure 1	Site Location Map
F ¹ A	

Figure 2 Site Plan

APPENDICES

Appendix A	Annual Checklist
Appendix B	NYC DOB Permits Issued
Appendix C	Inspection Photos



18-36 42[№] ST ASTORIA, NY 11105

718-545-0474 PHONE FAX

516-706-3214

I. EXECUTIVE SUMMARY

AMC Engineering (AMC) has prepared the following Periodic Review Report for the time period of April 27, 2019, to April 27, 2022, for the property located at 25 Kent Avenue in Brooklyn, New York 11249 under the New York State (NYS) Brownfield Cleanup Program (BCP) administered by the New York State Department of Environmental Conservation (NYSDEC). The Site was remediated in accordance with the Brownfield Cleanup Agreement (BCA) #C224207.

The concrete slab installed over the Track 2 portion of the Site designated as EP81, and the Track 2 portion of the Site designated as EP5 was inspected for evidence of cracking. No cracks or concrete slab penetrations were observed.

The Site does not rely on any mechanical systems, such as sub-slab depressurization systems or air sparge/soil vapor extraction systems to protect public health and the environment.



II. SITE OVERVIEW

A. Site Location

The Site is located in Kings County, New York City, New York and is identified as Block 2282 Lot 1 on the New York City Department of Assessment Tax Map. A United States Geological Survey (USGS) topographical quadrangle map (**Figure 1**) shows the Site location. The Site is an approximately 1.83-acre area and is bounded by North 13th Street to the north, North 12th Street to the south, Wythe Avenue to the east, and Kent Avenue to the west (see **Figure 2** – Site Layout Map).

B. Site Chronology

A Remedial Action Work Plan (RAWP) was prepared by AMC in December 2014, and revised in July 2015. The RAWP selected a Track 1 remedy for the Site consisting of the removal of all on-site soils which exceed the Unrestricted Use Soil Cleanup Objectives (SCOs), and provided for a Track 2 remedy to the extent Track 1 SCOs could not be achieved. The Department approved this remedy in its Decision Document of July 2015. The Remedial Action consisted of the following:

- Excavation of soil/fill exceeding Track 1 Unrestricted Use SCOs to development depths which averaged 24 feet below grade, with deeper remedial excavation in certain areas where end point samples at development depth exceeded Unrestricted Use SCOs;
- Screening for indications of contamination (by visual means, odor, and monitoring with PID) of all excavated soil during all intrusive Site work;
- Collection and analysis of end-point samples to evaluate the performance of the remedy with respect to attainment of Track 1 SCOs;
- Appropriate off-Site disposal of all material removed from the Site in accordance with all Federal, State, and local rules and regulations for handling, transport, and disposal;
- Dewatering and treatment of petroleum-impacted groundwater before discharging to the NYC sewer system under a NYCDEP sewer discharge permit;
- Import of ¾" clean stone and ¾" recycled concrete aggregate to be used for backfill below the building's concrete mat slab in compliance with: (1) chemical limitations and other specifications listed in the RAWP, and (2) all Federal, State, and local rules and regulations for handling and transport of material;
- In two areas in the southwestern corner of the Site, end point samples exceeded Track 1 SCOs, and samples obtained from test pits indicated that VOC impacts exceeding Track 1 SCOs extended to a depth below levels that could be safely excavated. Therefore, in those two areas, the building's 36 inch thick concrete mat slab serve as a composite cover system, and those areas of the Site are designated as Track 2;
- Development and implementation of a Site Management Plan for long term management of remaining contamination below the Track 2 portions of the Site which includes plans for: (1) Institutional Controls, (2) inspections and (3) reporting; and
- An Environmental Easement recorded on the two Track 2 portions of the Site will ensure implementation of the SMP.



III. REMEDY PERFORMANCE, EFFECTIVENESS & PROTECTIVENESS

The results of the end point soil samples collected after excavation of soils for remediation and for construction of the new buildings confirm that soil above Track 1 Unrestricted Use SCOs remains below the 36 inch thick concrete mat slab within the Track 2 portions of the Site. The Track 1 Unrestricted Use SCO exceedences consist of the VOCs benzene and ethylbenzene. Benzene was detected at a concentration of 700 ppb at the final excavation depth in the EP5 area, and at 750 ppb at the final excavation depth in the EP81 area. Deeper soil samples from below the final excavation depth were collected from the two Track 2 portions of the Site from test pits excavated to 6.5 feet (EP5) and 7 feet (EP81).

From the test pit excavated within the EP5 area, soil samples were collected representing the intervals 1 ft (EP5.1), 2 ft (EP5.2), 2.5 ft (EP5.3), 3 ft (EP5.3), 3.5 ft (EP5.4), 4 ft (EP5@4ft), 5ft (EP5@5ft), and 6.5ft (EP5@6.5 ft). Benzene was detected above the Track 1 Unrestricted Use SCO (60 ppb) within each of the soil samples, ranging in concentration from 300 ppb to 7,900 ppm. Ethylbenzene was only detected above the Track 1 Unrestricted Use SCO (1,000 ppb) within soil sample EP5@6.5ft (1,900 ppb).

From the test pit excavated within the EP81 area, soil samples were collected representing the intervals 1 ft (EP81.1), 2 ft (EP81.2), 5 ft (EP81@5ft), 6ft (EP81@6ft), and 7ft (EP81@7 ft). Benzene was detected above the Track 1 Unrestricted Use SCO within each of the soil samples, ranging in concentration from 340 ppb to 2,200 ppb.

The Track 1 Unrestricted Use SCO exceedences of benzene and ethylbenzene were encountered below a 3ft layer of peat moss and clay, and at depths greater than 15 feet below the groundwater table. Therefore, the Track 1 Unrestricted Use SCO exceedences of benzene and ethylbenzene are believed to be associated with an off-Site source which migrated onto the Site when the water table was approximately 15 feet lower than it is at the present time. The contaminants were forced upward as the water table rose and were entrained in the clay through the upward pressure gradient.

All soil at within the Track 2 portions of the site which remains above Unrestricted Use SCOs is capped with the site cover system consisting of a 36 inch thick concrete cellar mat slab underlain by a 32-mil waterproofing membrane, and a 4 inch thick concrete rat slab.



IV. IC PLAN COMPLIANCE REPORT

A1. IC Requirements and Compliance

1. IC Controls

A series of Institutional Controls (ICs), required under the Site Management Plan, were placed on the property in the form of an Environmental Easement which was recorded with the NYC Department of Finance, Office of the City Register (NYSDOF-OCR). The recorded ICs are as follows:

- prevent future exposure to residual contamination; and,
- limit the use and development of the Track 2 portions of the Site to restricted residential, commercial, or industrial uses only (as further described below), consistent with applicable zoning.

Adherence to these Institutional Controls on the Site (Controlled Property) is required under the Environmental Easement and are being implemented under the Site Management Plan. These Institutional Controls are:

- The Track 2 portion of the Site designated as EP81 may be used for: restricted residential, commercial, or industrial use;
- The Track 2 portion of the Site designated as EP5 may be used for: commercial, or industrial use;
- All ICs must be inspected at a frequency and in a manner defined in the SMP;
- The use of groundwater underlying the Track 2 portions of the Site is prohibited without necessary water quality treatment as determined by the NYSDOH to render it safe for its intended purpose, and the user must first notify and obtain written approval to do so from the Department;
- Compliance with the Environmental Easement by the Grantee and the Grantee's successors is required;
- The Owner of the Track 2 portions of the Site must, on the frequency required in Table 4 of the SMP, submit to NYSDEC a written statement that certifies, under penalty of perjury, that:

 (1) controls employed at the Site are unchanged from the previous certification or that any changes to the controls were approved by DEC; and, (2) nothing has occurred that impairs the ability of the controls to protect public health and the environment or that constitute a violation or failure to comply with the controls.
- All future activities that will disturb remaining contaminated material must be conducted in accordance with this SMP;
- Maintenance and inspection, and reporting of the composite cover system shall be performed as defined in this SMP;
- Access to the Track 2 portions of the Site must be provided to agents, employees or other representatives of the State of New York with reasonable prior notice to the property owner to assure compliance with the restrictions identified by the Environmental Easement; and



• Vegetable gardens and farming on the Track 2 portions of the Site are prohibited.

2. Status of each IC

The Environmental Easement, as described above, remains in place and has not been changed, revised or modified.

3. Corrective Measures

No deficiencies in the ICs were noted for this time period, therefore no corrective measures were required.

4. IC Conclusions and Recommendations

The Institutional Controls will continue to be inspected for the duration specified in the approved SMP. Since there are no Engineering Controls for Former Sunbelt Equipment, AMC recommends all future Periodic Review Reports include IC Certification only by an owner's representative (and not the Remedial Engineer).



A2. EC Requirements and Compliance

1. EC Controls

There are no Engineering Controls for Former Sunbelt Equipment.

2. Status of each EC

Not Applicable

3. Corrective Measures

Not Applicable

4. EC Conclusions and Recommendations

Not Applicable – Since there are no Engineering Controls for Former Sunbelt Equipment, AMC recommends all future Periodic Review Reports include IC Certification only by an owner's representative (and not the Remedial Engineer).



B. IC Certification

I, Ariel Czemerinski, am currently a registered professional engineer licensed by the State of New York. I have inspected the Engineering Controls for the Former Sunbelt Equipment site (NYSDEC Site No. C224207).

I certify that the composite cover system constructed over the Track 2 portions of the Site remain in-place and nothing has occurred to the composite cover system which would impair the ability of the composite cover system to protect the public health and the environment, or that would constitute a violation or failure to comply with any operation and maintenance of the composite cover system.

I certify that access is available to the NYSDEC and the NYSDOH to evaluate continued maintenance of the Engineering Controls.

I certify that the Institutional Controls in the form of an environmental easement recorded with the NYC Department of Finance, Office of the City Register, remains in place, is unchanged from the previous certification and that the current site usage is in compliance with the environmental easement.

NYS Professional Engineer #

Date

Signature



V. MAINTENANCE AND INSPECTION PLAN COMPLIANCE REPORT

A. Components of the Maintenance and Inspection Plan

The Site remedy does not rely on any mechanical systems, such as groundwater treatment systems, sub-slab depressurization systems or air sparge/soil vapor extraction systems to protect public health and the environment. Therefore, the operation and maintenance of such components was not included in the SMP.

The Maintenance and Inspection Plan describes the measures necessary to maintain the composite cover system and vapor barrier for the Site.

1. Composite Cover Inspection

Composite cover inspections for the Track 2 portions of the Site are to be performed at a minimum of once per year. Modification to the frequency or duration of the inspections will require approval from the NYSDEC. Composite cover inspections will also be performed after all severe weather conditions.

Inspections will also be performed in the event of an emergency. If an emergency, such as a natural disaster or an unforeseen failure of the composite cover system occurs that reduces or has the potential to reduce the effectiveness of the composite cover in place at the Site, verbal notice to the NYSDEC must be given by noon of the following day. In addition, an inspection of the Site will be conducted within 5 days of the event to verify the effectiveness of the composite cover implemented at the Track 2 portions of the Site by a qualified environmental professional, as determined by the NYSDEC. Written confirmation must be provided to the NYSDEC within 7 days of the event, and include a summary of actions taken, or to be taken, and the potential impact to the environment and the public.

Unscheduled inspections may take place when a suspected failure of the Composite Cover System has been reported or an emergency occurs that is deemed likely to affect the operation of the system. If any penetrations, holes, cracks or other disturbances are noted within the composite cover system repairs must be made immediately.

2. Reporting

A checklist is to be completed during each routine maintenance event which is scheduled to be on an annual basis. During these inspections, an inspection form will be completed to compile sufficient information to assess the following:

- Compliance with all ICs;
- An evaluation of the condition and continued effectiveness of the composite cover;
- General site conditions at the time of the inspection;
- The site management activities being conducted; and
- Confirm that site records are up to date.



18-36 42ND ST Astoria, NY 11105 PHONE 718-545-0474 FAX 516-706-3214 Composite cover inspections for the Track 2 portions of the Site will be conducted and documented annually, regardless of the frequency of the Periodic Review Report. The inspections will determine and document the following:

- Whether the composite cover continues to perform as designed;
- If the composite cover continues to be protective of human health and the environment;
- Compliance with requirements of this SMP and the Environmental Easement;
- Achievement of remedial performance criteria; and
- If site records are complete and up to date.

B. Summary of the Composite Cover Inspection Completed During Reporting Period

1. Composite Cover System

The concrete cellar mat slab over the Track 2 portions of the Site were inspected on August 4, 2020, September 15, 2021, and March 30, 2022.

C. Evaluation of Remedial Systems

1. Composite Cover System

No cracks, holes, perforations, or evidence of patching was noted during the inspection. The concrete slab appeared to be in new condition.

D. Composite Cover Deficiencies

There were no deficiencies in complying with the Maintenance and Inspection Plan during this PRR reporting period.

E. Conclusions and Recommendations for Improvements

No improvements in the Maintenance and Inspection Plan are necessary at this time. Since there are no Engineering Controls for Former Sunbelt Equipment, AMC recommends all future Periodic Review Reports include IC Certification only by an owner's representative (and not the Remedial Engineer).



VI. OVERALL PRR CONCLUSIONS AND RECOMMENDATIONS

A. Compliance with SMP

All requirements of the SMP were implemented during this PRR reporting period. In order to implement all of the SMP requirements, the following items were completed:

- The concrete cellar mat slab over the Track 2 portions of the Site were inspected and the checklist was completed.
- The ICs were inspected and the ICs were certified by the remedial engineer.


B. Future PRR Submittals


The next PRR submittal will reflect the PRR reporting period from the present until May 27, 2025. Since there are no Engineering Controls for Former Sunbelt Equipment, AMC recommends all future Periodic Review Reports include IC Certification only by an owner's representative (and not the Remedial Engineer).



<u>FIGURES</u>







<u>APPENDIX A</u> ANNUAL CHECKLISTS



PHONE 718-545-0474 FAX 516-706-3214

SITE INSPECTION CHECKLIST

Site Inspection Checklist - Cover System 25 Kent Avenue Brooklyn, NY Block 2282, Lot 1

Date:

20 Time: Brusser - EBC

Inspector Name/Organization:

Visual Inspection of Concrete Mat Slab

Inspect concrete/pavement for cracks, perforations and patching

Describe General Condition of Concrete

6000

Describe any Cracks or New Penetrations

VONE

Describe any Patching

VONE

Repairs Needed and / or Maintenance at this time?

NONE

26 2020 nl Signature: Date:

SITE INSPECTION CHECKLIST

Site Inspection Checklist - Cover System 25 Kent Avenue Brooklyn, NY Block 2282, Lot 1

Date: Set Zactime: 15

Inspector Name/Organization:

ussee 100

Visual Inspection of Concrete Mat Slab

Inspect concrete/pavement for cracks, perforations and patching

Describe General Condition of Concrete

doances-Slab is in

TO

es

Describe any Cracks or New Penetrations

Describe any Patching

ner n

Repairs Needed and / or Maintenance at this time?

PRAIS Nepdec Signature: Date:

SITE INSPECTION CHECKLIST

Site Inspection Checklist - Cover System 25 Kent Avenue Brooklyn, NY Block 2282, Lot 1

3-30-22 Time: Date: Inspector Name/Organization:

KEVIN BRUSSEE - EBC

Visual Inspection of Concrete Mat Slab

Inspect concrete/pavement for cracks, perforations and patching

Describe General Condition of Concrete

Describe any Cracks or New Penetrations

Describe any Patching

NONE

GOOD

VONE

Repairs Needed and / or Maintenance at this time?

VONE bur 202C Date: 130 Signature:

<u>APPENDIX B</u> <u>NYC DOB PERMITS</u>



Permit Number: 321730196-01-EW-OT Issued: 06/03/2019 Expires: 04/20/2020 Iddress: BROOKLYN 25 KENT AVENUE Issued to: JOSEPH ROMANO Address: BROOKLYN 25 KENT AVENUE Business: TRANSPARENT CONSTRUCTION Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. Business: TRANSPARENT CONSTRUCTION Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. Business: TRANSPARENT ALTERD HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY. BURDER OF WEILING DORS AS SHOWN ON Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of Work BITE FILL: NOT C	Issued: 06/03/2019 Issued to: JOSEPH ROMAN
Issued to: JOSEPH ROMANO Address: BROKLIN 25 KENT AVENUE Issueds to: JOSEPH ROMANO Description of Work: 25 KENT AVENUE Business: TRANSPARENT CONSTRUCTION Contractor No: GC-608891 Contractor No: GC-608891 Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - GEN: CONSTRUCT INTERIOR INTERIOR CONCRETE PLACEMENT, PRANTINGS FILED HERENITH. NO CHANGE IN USP, GERESS OR OCCUPANCY. Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Review is requested under Building Supernut web site at www.nyc.gov/building. Not Review 1732009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 7132009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 7132009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 700000, please use "Wy Community" on the Building Supernet of Buildings. <th></th>	
Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - GEN. CONSTRUCT INTERIOR PARTITIONS, CELLINGS AND DOORS AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY. Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of proventing Data and the Building Code: 2008 Number of proventing SITE FILL: NOT APPLICABLE National Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7(132009, please use "Ny Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 31 Borough Commissioner: Trias formissioner: Trias operated on 06/03/2019 reflects the Commissioner (s) as of such date. Tampering with or knowingly making a flase entry in or falsely aftering this permit is a crime that is purishable by a fine, imprisonal permissioner	BROOKLYN 25 KENT AVENUE
Number of dwelling units occupied during construction: 0 Review is requested under Building Code: 2008 SITE FILL: NOT APPLICABLE To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "Ny Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 311 Commissioner of a New Buildings. Borough Commissioner: Commissioner of Buildings. This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely attering this permit is a crime that is punishable by a fine, imprisograph of 50/1010	CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED.
To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 311 Emergency Telephone Day or Night: 311 Borough Commissioner: Commissioner of Buildings: Mac Commissioner of Buildings: This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisograph of 03/2019 (1000) 1000 (1000) 1	of dwelling units occupied during construction: 0
Emergency Telephone Day or Night: 311 Borough Commissioner: Commissioner of Buildings: Macle Commissioner of Buildings: Macle Commissioner (s) as of such date. This permit copy created on 06/03/2019 reflects the Commissioner (s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment for both or both of the commissioner (s) as of such date.	To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings.
This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both.	311 Commissioner of Buildings:
	/03/2019 reflects the Commissioner(s) as of such date. falsely altering this permit is a crime that is punishable by a fine, imprisonment 9

Permit Number: 321730196-01-EW-OT Issued: 06/03/2019 Expires: 04/20/2020 Iddress: BROOKLYN 25 KENT AVENUE Issued to: JOSEPH ROMANO Address: BROOKLYN 25 KENT AVENUE Business: TRANSPARENT CONSTRUCTION Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. Business: TRANSPARENT CONSTRUCTION Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. Business: TRANSPARENT ALTERD HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY. BURDER OF WEILING DORS AS SHOWN ON Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 BITE FILL: NOT APPLICABLE BITE FILL: NOT APPLICABLE Number of Work BITE FILL: NOT C	Issued: 06/03/2019 Issued to: JOSEPH ROMAN
Issued to: JOSEPH ROMANO Address: BROKLIN 25 KENT AVENUE Issueds to: JOSEPH ROMANO Description of Work: 25 KENT AVENUE Business: TRANSPARENT CONSTRUCTION Contractor No: GC-608891 Contractor No: GC-608891 Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - GEN: CONSTRUCT INTERIOR INTERIOR CONCRETE PLACEMENT, PRANTINGS FILED HERENITH. NO CHANGE IN USP, GERESS OR OCCUPANCY. Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Review is requested under Building Supernut web site at www.nyc.gov/building. Not Review 1732009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 7132009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 7132009, please use "Wy Community" on the Building Supernet web site at www.nyc.gov/buildings. Mcdefination filed after 700000, please use "Wy Community" on the Building Supernet of Buildings. <th></th>	
Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - GEN. CONSTRUCT INTERIOR PARTITIONS, CELLINGS AND DOORS AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY. Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of dwelling units occupied during construction: 0 SITE FILL: NOT APPLICABLE Number of proventing Data and the Building Code: 2008 Number of proventing SITE FILL: NOT APPLICABLE National Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7(132009, please use "Ny Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 31 Borough Commissioner: Trias formissioner: Trias operated on 06/03/2019 reflects the Commissioner (s) as of such date. Tampering with or knowingly making a flase entry in or falsely aftering this permit is a crime that is purishable by a fine, imprisonal permissioner	BROOKLYN 25 KENT AVENUE
Number of dwelling units occupied during construction: 0 Review is requested under Building Code: 2008 SITE FILL: NOT APPLICABLE To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "Ny Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 311 Commissioner of a New Buildings. Borough Commissioner: Commissioner of Buildings. This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely attering this permit is a crime that is punishable by a fine, imprisograph of 50/1010	CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED.
To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings. Emergency Telephone Day or Night: 311 Emergency Telephone Day or Night: 311 Borough Commissioner: Commissioner of Buildings: Mac Commissioner of Buildings: This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisograph of 03/2019 (1000) 1000 (1000) 1	of dwelling units occupied during construction: 0
Emergency Telephone Day or Night: 311 Borough Commissioner: Commissioner of Buildings: Macle Commissioner of Buildings: Macle Commissioner (s) as of such date. This permit copy created on 06/03/2019 reflects the Commissioner (s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment for both or both of the commissioner (s) as of such date.	To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings.
This permit copy created on 06/03/2019 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both.	311 Commissioner of Buildings:
	/03/2019 reflects the Commissioner(s) as of such date. falsely altering this permit is a crime that is punishable by a fine, imprisonment 9

Buildings
Work Permit Department of Buildings
Permit Number: 340739017-01-Ем-ОТ [Issued: 07/21/2020 Expires: 05/27/2021
Issued to: MARISSA LIEBHABER Address: Brooklyn 25 kent Avenue Business: LINEAGE CONSTRUCTION LLC
WORK NC
FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - ARCH HEREBY FILING TO CONSTRUCT A NEW ROOFTOP AMENITY SPACE AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE IN USE, EGRESS OR OCCUPANCY.
0 - 1625- 0 0 - 1625- 0
Number of dwelling units occupied during construction: 0 Review is requested under Building Code: 2008 SITE FILL: NOT APPLICABLE
To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings.
Emergency Telephone Day or Night: 311 Borough Commissioner of Buildings: McC S. MC
py created on 07/24/2020 re naking a false entry in or falsely altering t

OP-35A (5/10)





Work Permit Department Of Buildings

SIV-II-9£££6008	SJV-11-9222	Issued: 07.05/2020
Address: BROOKLYN 25 KENT AVENUE	25 KENT AVENUE	Expires: 05/20/2020
Work on Floor(s): FLO	Work on Floor(s): FLOOR NUMBER(S) 003 THROUGH 003	Issued To: VASKO ZADRIMA
		Business: BLACK BULL BULDERS LLC
		License No: GC-610827
Total number of dwelling units at location: 0	units at location: 0	
Number of dwelling units	Number of dwelling units occupied during construction: 0	
Description: SHO	HEREBY FILING TO MODIFY DUCTWORK AND PIPING FOR HVAC SYSTEM IN THE 3RD FLOOR PUBLIC CORRIDOR AS SHOWN ON PLANS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY OR EGRESS.	AC SYSTEM IN THE 3RD FLOOR PUBLIC CORRIDOR AS CUPANCY OR EGRESS.
	For detailed information regarding this permit, please log on to DOB NOW at www.nyc.gov/buildings. Call 311 with any questions or complaints.	B NOW at www.nyc.gov/buildings. laints.

Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both.

Borough Commissioner:

Commissioner of Buildings: Nec 5





Buildings

Department Of Buildings Work Permit

	T
Permit Number: BU0280055-11-NIS	Issued: 02/25/2020
Address: BROOKLYN 25 KENT AVENUE	Expires: 12/21/2020
Work on Floor(s): CELLAR	Issued To: VASKO ZADRIMA
	Business: BLACK BULL BULDERS LLC
	License No: GC-610827
Total number of dwelling units at location: 0	
Number of dwelling units occupied during construction: 0	
Description: HEREBY FILING TO MODIFY DUCTWORK AND PIPING AND INSTALL NEW HVAC SYSTEM I SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY, OR EGRESS.	HEREBY FILING TO MODIFY DUCTWORK AND PIPING AND INSTALL NEW HVAC SYSTEM FOR FITNESS CENTER AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY, OR EGRESS.
and show the design of the second s	

Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both

2

Borough Commissioner:

5 3

has

Commissioner of Buildings:

For detailed information regarding this permit, please log on to DOB NOW at www.nyc.gov/buildings. Call 311 with any questions or complaints.





Buildings

Department Of Buildings Work Permit

HEREBY FILING TO MODIFY DUCTWORK AND PIPING AND INSTALL NEW HVAC SYSTEM FOR FITNESS CENTER AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY, OR EGRESS.	Description: HEREBY FILING TO MODIFY DUCTWOR SHOWN ON DRAWINGS FILED HEREWITH
	Number of dwelling units occupied during construction: 0
CV-1625- 00%	Total number of dwelling units at location: 0
License No: GC-610827	GILLE
BUACK BULL BULDERS LLC	
Issued To: VASKO ZADRIMA	Work on Floor(s): CELLAR
Expires: 05/20/2020	Address: BROOKLYN 25 KENT AVENUE

Borough Commissioner:

とい

Commissioner of Buildings: Nucl

Call 311 with any questions or complaints.

Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both.

2

Buildings
Work Permit Department of Buildings
Permit Number: 321750869-01-EW-OT Issued: 02/14/2020 Expires: 12/21/2020 Issued to: VASKO ZADRIMA Address: BROOKLYN 25 KENT AVENUE Business: BLACK BULL BULDERS LLC
Contractor No: GC-610827 Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FORMWORK, STEEL REINFORCING NOT PERMITTED. ALTERATION TYPE 2 - ARCH HEREBY FILING TO REMOVE AND INSTALL INTERIOR PARTITIONS, CEILINGS AND DOORS FOR FITNESS CENTER AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE IN USE, EGRESS OR DOCUPANCY.
Number of dwelling units occupied during construction: 0 Review is requested under Building Code: 2008 SITE FILL: NOT APPLICABLE
To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings.
Emergency Telephone Day or Night: 311 311 Borough Commissioner: Mm. Commissioner of Buildings: This permit copy created on 02/14/2020 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisognent 91 both.

Buildings
Work Permit Department of Buildings
Permit Number: 321750878-01-EW-OT
Issued to: VASKO ZADRIMA Address: BROOKLYN 25 KENT AVENUE Business: BLACK BULL BULDERS LLC
Contractor No: GC-610827 Description of Work: CONCRETE WORK NOT AUTHORIZED - CONCRETE PLACEMENT, FODMMODY STRENDCING NOT DEDMITTED
BY FILING HANGE IN
Number of dwelling units occupied during construction: 0 Review is requested under Building Code: 2008
To see a Zoning Diagram (ZD1) or to challenge a zoning approval filed as part of a New Building application or Alteration application filed after 7/13/2009, please use "My Community" on the Buildings Department web site at www.nyc.gov/buildings.
Emergency Telephone Day or Night: 311
Commissioner of Buildings:
This permit copy created on 02/06/2020 reflects the Commissioner(s) as of such date. Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment of both, 200

OP-35A (5/10)





Work Permit Department Of Buildings Buildings

Permit Number: B00280102-II-PL Issued: 03/11/2020 Address: BROOKLYN 25 KENT AVENUE Expires: 04/25/2020 Mork on Floor(s): CELLAR Expires: 04/25/2020 Work on Floor(s): CELLAR Expires: 04/25/2020 Work on Floor(s): CELLAR Expires: 04/25/2020 Vork on Floor(s): CELLAR Expires: 04/25/2020 Vork on Floor(s): CELLAR Expires: NARC BRESLAW Vork on Floor(s): CELLAR Expires: NARC BRESLAW Vork on Floor(s): CELLAR Distance Distance Vork on Floor(s): CELLAR Distance Distance Vork on Floor(s): 0 Number of dwelling units at location: 0 Number of dwelling units occupied during construction: 0 No Distance Description: HERBY FILING TO REMOVE, INSTALLAND RELOCATE PLUMBING FINTURES, SPRINKLER HEADS AND RELATED Description: PIPING FOR THE FITINESS CENTER AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY
--

I Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both. Commissioner of Buildings: Necl. 5.K call otta while any questions of compliantics. -**Borough Commissioner:**





Work Permit Department Of Buildings Buildings

Permit Number: B00280102-II-EW-SP	Issued: 03/10/2020
Address: BROOKLYN 25 KENT AVENUE	Expires: 04/25/2020
Work on Floor(s): CELLAR	Issued To: MARC BRESLAW
	Business: TRISTATE PLBG SVCS CORP
	License No: F-000522
Total number of dwelling units at location: 0	
Number of dwelling units occupied during construction: 0	
Description: HEREBY FILING TO REMOVE, INSTALLAND RELOCATE PLUMBING FIXTURES, SPRINKLER HEADS AND RELATED PIPING FOR THE FITNESS CENTER AS SHOWN ON DRAWINGS FILED HEREWITH. NO CHANGE TO USE, OCCUPANCY OR EGRESS.	NG FIXTURES, SPRINKLER HEADS AND RELATED LED HEREWITH. NO CHANGE TO USE, OCCUPANCY
For detailed information regarding this permit, please log on to DOB NOW at www.nyc.gov/buildings. Call 311 with any questions or complaints.	NOW at www.nyc.gov/buildings. ints.
Borough Commissioner:	Commissioner of Buildings: New S.M.

Tampering with or knowingly making a false entry in or falsely altering this permit is a crime that is punishable by a fine, imprisonment or both.

<u>APPENDIX C</u> INSPECTION PHOTOS











