LANGAN SITE OBSERVATION REPORT - Day 218

Gowanus Canal LLC,

CLIENT: GowCan Owner, LLC, and Bayside

Gowanus Owner, L.L.C.

PROJECT No.: 170295301

> Gowanus Canal Northside TIME:

LOCATION: Brooklyn, New York

BCP SITE ID:

DATE:

WEATHER:

Komatsu PC 490 Excavator Komatsu PC 240 Excavator

Komatsu PC 78 US Excavator Komatsu Wheel Loader Komatsu PC 490 Excavator Manitou MRT 3255 Crane

Liebherr Crane

PROJECT:

EQUIPMENT:

PRESENT AT SITE:

Langan: Tom Herold (Environmental) Urban Atelier Group (UAG): Seth Anderson

C224080

Kingdom Associates, Inc. (Kingdom): George Minchala TT Mechanical Corp. (TT Mechanical): Damien Sokol

Saturday, June 24, 2023

Wind: SSW @ 5 - 7 mph

Overcast, 69 - 78 °F

07:00 - 16:00

WSP: Brian Jessourian

OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:

Langan was on-site to document implementation of the New York State Department of Environmental Conservation (NYSDEC)-approved March 24, 2022 Remedial Action Work Plan (RAWP) for Brownfield Cleanup Program (BCP) Site No. C224080. Site Map 1 presents the Society Brooklyn and Sackett Place developments, which together comprise the BCP site.

Site Activities

Kingdom performed utility installation-related work in the Sackett Street right-of-way outside the BCP boundary as part of development-related construction. This work is not part of RAWP implementation.

Import and Export Tracking

- No material was imported to the site.
- No material was exported from the site.

Soil/Fill Export Summary			
Facility	Exported Today		Total
Bayshore Soil Management	No. Loads	0	764
Keasbey, NJ Non-Hazardous Soil/Fill	Quantity (CY)	0	15,280
Bayshore Soil Management Keasbey, NJ Non-Hazardous MGP-Impacted Soil/Fill	No. Loads	0	79
	Quantity (CY)	0	1,580
Phase III Environmental Palmerton, PA Non-Hazardous Soil/Fill	No. Loads	0	67
	Quantity (CY)	0	1,340

Cc:	J. Hayes, M. Burke, P. Farnham, E. Adkins, A.	Ву:	Tom Herold
	Nesci		Langan, D.P.C.

Material Import Summary				
Facility	NYSDEC Approved Quantity (CY)	Imported	Today	Total
Stavola Construction Materials, Inc		No. Loads	0	15
Bridgewater, NJ 2.5-inch Stone	1,000	Quantity (CY)	0	300
87 19 th Avenue	2,000	No. Loads	0	31
Astoria, NY 2.5-inch Stone		Quantity (CY)	0	650
Impact Environmental Jersey City, NJ	5,000	No. Loads	0	224
0.5-inch Crushed Stone		Quantity (CY)	0	4,480
Impact Environmental	6,000	No. Loads	0	48
Lyndhurst, NJ 0.5-inch Crushed Stone		Quantity (CY)	0	960
Impact Environmental	4.000	No. Loads	0	29
Lyndhurst, NJ 4,000 0.75-inch Crushed Stone	Quantity (CY)	0	580	
Tilcon New York Inc.	Wharton, NJ 3,500	No. Loads	0	95
Wharton, NJ ASTM #5 Virgin Quarry Stone		Quantity (CY)	0	1,900

Sampling

• No samples were collected.

Community Air Monitoring

• Ground intrusive work was not performed within the BCP site boundary, and thus community air monitoring was not implemented. No dust or odors were apparent on-site.

Anticipated Activities

• Kingdom will continue to perform utility-related work in Sackett Street.

Cc:	J. Hayes, M. Burke, P. Farnham, E. Adkins, A.	Ву:	Tom Herold
	Nesci		Langan, D.P.C.

Site Photographs



Photo 1: General view of the Shore Public Walkway (SPW) (facing north)



Photo 2: View of stockpile covered with polyethylene sheeting within the SPW (facing north)

Cc:	J. Hayes, M. Burke, P. Farnham, E. Adkins, A.	Ву:	Tom Herold
	Nesci		Langan, D.P.C.

Site Map 1: **DEGRAW STREET Society Brooklyn** BOND STREET **GOWANUS CANAL** SACKETT STREET **UNION STREET** Legend Approximate BCP site boundary --- Approximate construction fence boundary Notes Base map adapted from 24 March 2022 RAWP, Figure 2 – Site Plan. 1. This Site Map is provided for context only; refer to the Northern (Society Brooklyn) and Southern (Sackett Place) Work Area Maps on the following pages for work and air monitoring location(s). Cc: J. Hayes, M. Burke, P. Farnham, E. Adkins, A. By: Tom Herold Nesci Langan, D.P.C.



