



DAILY STATUS REPORT

Prepared by: Alex Keenan

WEATHER	Snow		Rain		Overcast		Partly Cloudy		Bright Sun	x
TEMP.	< 32		32-50		50-70		70-85		> 85	

DEC BCP Project. No.	C224350	Date:	10/11/22
Project Name:	318 Nevins Street, Brooklyn, NY		

Environmental Consultant: Impact Environmental Closures, Inc 170 Keyland Court Bohemia, NY 11716.	Environmental Safety Officer: Thomas Jensen– Impact Environmental Closures, Inc.
General Contractor: Broadway Construction Group, LLC	Site Manager/ Supervisor: Site Super: Shannon Dowling- Broadway Construction Group, LLC Diana Posten– Impact Environmental Closures, Inc.
Work Activities Performed (Since Last Report) <ul style="list-style-type: none">Impact arrived on site at 0815 and held Health and Safety meeting with PG Environmental; andImpact Environmental purged GW-3 and GW-7 as well as collected gw sample from each of the wells using low-flow techniques <p>*It should be noted that since the start of this RI work (9/27/22), the portion of the Gowanus Canal adjacent to the Site has been getting dredged.</p>	
Working In Area: <ul style="list-style-type: none">Western portion of the Site.	

Samples Collected (Since Last Report): <ul style="list-style-type: none">GW-3GW-7 <p>*All required QA/QC samples were collected.</p>
Air Monitoring (Since Last Report): <p>CAMP was not run as no subsurface intrusive work was occurring on this date.</p>
Problems Encountered: <ul style="list-style-type: none">None
Planned Activities for the Next Day/ Week: <ul style="list-style-type: none">Finish sampling all ground water monitoring wells; andCollect GPS coordinates for all sample locations.

Site Grid Map




Photo Log

Photo 1 – Representative photo of pre-sampling set-up at GW-3.



Photo 2 – Representative photo of pre sampling, low flow set-up at well GW-7.

