

DAILY FIELD REPORT

Project	Former A&A Brake Service Site	Report No.	13
BCP Site	NYSDEC BCP SITE C224372	Date	6/15/2023
Location	558 Sackett Street	ett Street File No.	
Client	Sackett Heights LLC	Temperature	H:80 L: 60
Contractor	STAR Demolition	Wind Direction	NW to SE 10 mph
Weather	Sunny	Personnel on Site	Eddy Nunez
Humidity	48%	Time on Site	7:30-15:00

Haley & Aldrich of New York (Haley & Aldrich) was present to document implementation of the NYSDEC-Approved Remedial Investigation Work Plan (RIWP) dated March 2023. Site observations are summarized below.

Daily Observations:

 Contractor loaded twelve (12) loads of C&D debris for transport and disposal to Cooper Recycling Center in Brooklyn, NY.

CAMP Activities:

 Air monitoring was performed at one upwind and one downwind location during demolition activities. No 15-minute average concentration of volatiles organic compounds (VOCs) or particulate 15-minute average concentration of matter smaller than 10 microns in diameter (PM10) exceeded the action levels. No visible dust was observed leaving the site perimeter.

Activities Planned for Coming Week:

 Continued demolition of 	of the site.
---	--------------



DAILY FIELD REPORT

Site Photographs:



Photo 1: View of air monitoring setup.



Photo 2: View of site, facing south.



DAILY FIELD REPORT



558 Sackett Street, Brooklyn, NY **BCP Site C224372 Air Monitoring Log**

Date: 6/15/2023

Personnel: Eddy Nunez Weather: 60-80 deg F, Sunny

Humidity: 48% Wind Direction: NW to SE 10 mph

> Particulate Background (mcg/m3): 0.005

PID Background (ppm):









	Particulate		V	VOCs		Notes
	Upwind	Downwind	Upwind	Downwind	Notes	
Time	(mcg/m3)	(mcg/m3)	(ppm)	(ppm)	Odors (y/n)	Activities/Additional Monitoring
630						
645						
700						
715						
730						Site preparation/equipment
745						organization - demolition work not
800						implented
815						
830						
845	0.02	0.005	0	0	n	Demolition Work beings at site
900	0.023	006	0	0	n	
915	0.021	0.007	0	0	n	
930	0.024	0.014	0	0	n	
945	0.03	0.025	0	0	n	
1000	0.034	0.027	0	0	n	
1015	0.04	0.022	0	0	n	
1030		0.024	0	0	n	
1045	0.04	0.028	0	0	n	

558 Sackett Street, Brooklyn, NY BCP Site C224372 Air Monitoring Log

	Particulate		V	VOCs		Notes	
	Upwind	Downwind	Upwind	Downwind		Notes	
Time	(mcg/m3)	(mcg/m3)	(ppm)	(ppm)	Odors (y/n)	Activities/Additional Monitoring	
1100							
1115							
1130						Break in site activities between truck	
1145						rounds; visual and olfactory	
1200						monitoring conducted	
1215							
1230							
1245	0.045	0.03	0	0	n		
1300	0.051	0.035	0	0	n		
1315	0.06	0.038	0	0	n		
1330	0.067	0.031	0	0	n		
1345	0.058	0.044	0	0	n		
1400	0.051	0.04	0	0	n		
1430	0.056	0.037	0	0	n		
1445	0.055	0.035	0	0	n		
1500	0.049	0.033	0	0	n		
1515							
1530							
1545							
1600							
1615							
1630							
1645							
1700							
1715							
1730							
1745							
1800							
1815							
1830							
1845							