

## SITE OBSERVATION REPORT

PROJECT: 250 Water Street CLIENT: Clear, 70-80 °F WEATHER: Wind: WSW @ 0.8 mph (9:16am)

CLIENT: WEATHER: WING: VVSVV @ 0.8 mph (9:16an to SSW @ 6.2 mph (11:45am)

LOCATION: New York, NY

**TIME:** 8:30 am – 3:00 pm

**CONTRACTOR:** La Life Paving, Inc. (La Life Paving) LANGAN REP.: Tomas Monti, Adrian Heath

EQUIPMENT: PRESENT AT SITE:

Bobcat S770 Tomas Monti, Adrian Heath – Langan

Compactor Antonio Agro – La Life Paving

MiniRAE 3000 Dusttrak DRX

### **OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.:**

Langan continued documenting the parking lot repairs in accordance with the New York State Department of Environmental Conservation (NYSDEC)-approved June 8, 2021 Parking Lot Repair Work Plan for NYSDEC Brownfield Cleanup Program (BCP) Site No. C231127 located at 250 Water Street (Block 98, Lot 1).

### **Site Activities**

Jerome J505 and J405

- La Life Paving cut edges in the existing asphalt around the perimeter of the weathered areas in the eastern part of the site.
- La Life Paving cleaned and removed loose asphalt and placed asphalt cement (AC-5) at the weathered areas in the eastern part of the site.
- La Life Paving placed and compacted a 1.5-inch layer of asphalt in the weathered areas in the eastern part of the site.

#### Material Tracking

- No material was imported to the site.
- No material was exported from the site.

#### Sampling

No samples were collected.

Cc:	J. Yanowitz, P. McMahon, M. Raygorodetsky	Ву:	Tomas Monti
			LANGAN



Langan PN: 170381202 Tuesday, June 15, 2021

Page 2 of 4

## SITE OBSERVATION REPORT

# **CAMP Activities**

Langan performed air monitoring during parking lot repair activities. Fifteen-minute average concentrations of particulate matter smaller than 10 microns in diameter (PM10), mercury vapor, and volatile organic compounds (VOC) did not exceed action levels for the duration of work activities. Daily background concentrations for PM10, VOCs, and mercury vapor based on the June 16, 2020 baseline air monitoring event were 0.025 milligrams per cubic meter (mg/m³) for PM10, 0.5 parts per million (ppm) for VOCs, and 0.0 micrograms per cubic meter (µg/m³) for mercury vapor.

Daily Average Concentrations						
Station ID	Particulate (mg/m³)	Organic Vapor (ppm)	Mercury Vapor (µg/m³)			
PM-1	0.013	0.0	0.0			
PM-2	0.019	0.0	0.0			
PM-3	0.018	0.0	0.0			
PM-4	0.035	0.1	0.0			
PM-5	0.027	0.0	0.0			
PM-6	0.013	0.0	0.0			
WZ-1	0.042	0.4	0.0			

Maximum 15-Minute-Average Concentration						
Station ID	Particulate (mg/m³)	Organic Vapor (ppm)	Mercury Vapor (µg/m³)			
PM-1	0.035	0.0	0.0			
PM-2	0.067	0.1	0.0			
PM-3	0.044	0.0	0.0			
PM-4	0.110	0.2	0.0			
PM-5	0.068	0.0	0.0			
PM-6	0.027	0.0	0.8			
WZ-1	0.100	1.9	0.0			

## **Anticipated Activities**

• La Life Paving will pave the depressed areas with asphalt.


			LANGAN
Cc:	J. Yanowitz, P. McMahon, M. Raygorodetsky	By:	Tomas Monti



Langan PN: 170381202 Tuesday, June 15, 2021

Page 3 of 4

# SITE OBSERVATION REPORT



# Legend:



Approximate location of air monitoring station (on-site)



Approximate location of air monitoring station (off-site)



Approximate locations of work zone air monitoring station



Approximate location of parking lot surface repair

### Notes:

 Air monitoring station were relocated based on work area and wind direction. Locations shown above identify the predominant area of the air monitoring station.

Cc:	J. Yanowitz, P. McMahon, M. Raygorodetsky	Ву:	Tomas Monti
			LANGAN



Langan PN: 170381202 Tuesday, June 15, 2021

Page 4 of 4

# SITE OBSERVATION REPORT

# Select Site Photographs:



Photo 1: View of cut edges in the existing asphalt and placement of AC-5 (facing project southwest)




Photo 2: View of backfilling and compaction of a 1.5-inch asphalt layer (facing project northeast)

Cc:	J. Yanowitz, P. McMahon, M. Raygorodetsky	Ву:	Tomas Monti
			LANGAN