

APPENDIX U

RESIDUAL CONTAMINATION SURVEY COORDINATES

APPENDIX U
 SURVEY COORDINATES FOR RESIDUAL CONTAMINANTS LEFT IN-PLACE
 FINAL ENGINEERING REPORT
 ATLAS PARK - PARCEL B
 GLENDALE, NY

Residual Contaminant Location	X-Coord	Y-Coord
BUILDING 3 B3-Pipe1-1	-164.8777	-150.7043
BUILDING 7 B7-1-9.5-10 B7-5-9-9.5 B7-5E-9-9.5 Bldg28-GP1A Bldg28-GP3A Bldg28-GP4A B48-2-4 EP(SW)-I3-122904	-551.4673 -566.4845 -561.0237 -499.1108 -503.685 -507.6874 -432.6687 -478.4739	-76.415 -37.6995 -55.9185 -59.89 -47.7988 -26.8554 -70.9493 -140.5715
BUILDING 8 UST1-BOT UST1-NSW CONED-BOT1 B51-2-4	-825.8414 -818.1951 -760.4232 -668.3123	-243.176 -244.8736 -150.6585 -178.4447

Notes.

- 1) Coordinates are relative to the Site benchmark set as the "Project Zero"
(N40 42.550; W73 52.183)