#### **Monthly Progress Report No. 57**

43-02 to 43-40 24<sup>th</sup> Street, Long Island City, New York Long Island City Center Brownfield Cleanup Program Site #: C241189 Reporting Period: January 2023

#### 1. Introduction

In accordance with the reporting requirements of the 8 December 2016 Brownfield Site Cleanup Agreement (BCA) (amended 13 May 2022) for the above-referenced site, Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) prepared this monthly progress report, on behalf of CP VIII LIC Owner, LLC (the Volunteer), to summarize the work performed at 43-02 to 43-40 24<sup>th</sup> Street, Long Island City, New York (the site) from January 1 to 31, 2022.

The site, Long Island City Center, consists of one trapezoidal-shaped lot (Queens Tax Map Block 436, Lot 1) encompassing about 58,600 square feet (±1.3 acres). The site was formerly improved by a two-story warehouse building and a one-story parking garage. The parking garage was demolished in August 2016 and the warehouse building was demolished in April 2017. The site is bound by a 5-story office building and a construction site followed by 43<sup>rd</sup> Avenue to the north, 23<sup>rd</sup> Street to the west, 44<sup>th</sup> Road to the south, and 24<sup>th</sup> Street to the east. The elevated New York City Transit Authority (NYCTA) No. 7 subway structure runs along 23<sup>rd</sup> Street. Land use within a half mile of the site is urbanized and includes residential, commercial and industrial buildings, cross streets, subway tunnels and elevated railways, government buildings, and school facilities.

### 2. Remedial Actions Relative to the Site during this Reporting Period

Langan continued implementing the New York State Department of Environmental Conservation (NYSDEC)-approved Remedial Action Work Plan (RAWP) during the reporting period. The following were completed:

- The foundation contractor (ECD) and soil broker (EE) continued installing lagging associated with the support of excavation (SOE) system.
- ECD/EE poured concrete mud slab, pile caps, grade beams, foundation walls, and cellar slab in the central, northern and eastern parts of the site.
- ECD/EE continued installing vapor barrier/waterproofing, consisting of GCP Preprufe vapor barrier and GCP Bituthene liquid membrane, in the northern, eastern and western parts of the site.
- ECD/EE excavated and disposed of approximately 1,940 cubic yards of non-hazardous soil/fill from waste characterization grids COMP A, B, C, D, E2, F, G, I, J, J2, K, L, N, and O. Material was disposed of at Middlesex County Utilities Authority Landfill (MCUA) in East Brunswick, NJ.
- ECD/EE excavated and disposed of approximately 640 cubic yards of non-hazardous soil/fill from waste characterization grids COMP E2 and I. Material was disposed of at P Park NJ LLC (PPark) in Prospect Park, NJ.

- ECD/EE imported approximately 125.46 tons of NYSDEC-approved 2" 4" Tracking Pad Stone from the off-site permitted facility, Braen Aggregates, LLC of Franklin, NJ. Imported material was used to fortify the tracking pads in the southwestern and southeastern parts of the site.
- ECD/EE imported approximately 302.46 tons of NYSDEC-approved 2" 4" Tracking Pad Stone from the off-site permitted facility, Stone Industries, Inc. of Haledon, NJ. Imported material was used to fortify the tracking pads in the southwestern and southeastern parts of the site.
- ECD/EE imported approximately 649.75 tons of NYSDEC-approved ASTM#57 Stone from
  the off-site permitted facility, Tilcon New York, Incl. Mt. Hope Quarry of Wharton, NJ.
  Imported material was used to fortify the tracking pads in the southwestern and
  southeastern parts of the site, to support the soil mix wall in the central part of the site,
  and to backfill around forms and excavations as needed.
- ECD/EE imported approximately 24.30 tons of NYSDEC-approved ASTM#57 Stone from the off-site permitted facility, Stone Industries, Inc. of Haledon, NJ. Imported material was used to fortify the tracking pads in the southwestern and southeastern parts of the site.
- Langan collected four documentation endpoint samples and one confirmation endpoint sample (discussed below).

#### 3. Actions Relative to the Site Anticipated for the Next Reporting Period

Foundation construction and implementation of the NYSDEC-approved RAWP will continue during the next reporting period.

#### 4. Approved Activity Modifications (changes of work scope and/or schedule)

None.

#### 5. Results of Sampling, Testing and Other Relevant Data

One documentation endpoint sample was collected on January 4, 2023 (EP19\_1). The sample was submitted for analysis to York Analytical Laboratories, Inc. (York) of Stratford, Connecticut for mercury analysis. Mercury was not detected above NYSDEC Part 375 Restricted Use Restricted-Residential Soil Cleanup Objectives (RRU SCOs).

Three documentation endpoint samples were collected on January 5, 2023 (EP18\_1.5, EP12\_5.8, and EP19\_-5.8). Sample EP18\_1.5 was submitted to York for semi-volatile organic compounds (SVOCs) and metals (including hexavalent chromium and cyanide) analysis. Samples EP12\_-5.8 and EP19\_-5.8 were submitted to York for per-and polyfluoroalkyl substances (PFAS, via method EPA 1633) analysis. No analytes were detected above NYSDEC Part 375 RRU SCOs or PFAS Guidance Values.

One confirmation endpoint sample was collected on January 24, 2023 (EP24\_4). The sample was submitted for analysis to York for the Part 375 volatile organic compounds (VOCs), SVOCs, Metals (including hexavalent chromium and cyanide), polychlorinated biphenyls (PCBs), PFAS (EPA 1633), 1,4-dioxane, and Pesticides/Herbicides. No analytes were detected above NYSDEC Part 375 RRU SCOs or PFAS Guidance Values.

#### 6. Deliverables Submitted During This Reporting Period

Site Observation Reports were submitted to summarize activities completed in January 2023.

#### 7. Information Regarding Percentage of Completion

This Brownfield Cleanup Program (BCP) project is about 80% complete.

## 8. Unresolved Delays Encountered or Anticipated That May Affect the Schedule and Mitigation Effort

There were no delays encountered during this reporting period.

## 9. Community Participation (CP) Plan Activities during This Reporting Period

There were no CP Plan activities completed during this reporting period.

#### 10. Activities Anticipated in Support of the CP Plan for the Next Reporting Period:

Activities supporting the CP Plan are not anticipated during the next reporting period.

#### 11. Miscellaneous Information

None.

## **Estimated Project Schedule**

# Long Island City Center Queens, NY

			2022							2023												
ltem	Action	JAN	FEB	MAR	APR	MAY	NOC	AUG	SEP	ОСТ	NOV	DEC	JAN	FEB	MAN	MAY	NOC	nr	AUG	SEP	100	DEC
1	Site Mobilization																					
2	421a Foundation Element Installation																					
3	RAWP Implementation/Construction		-																			
4	FER, SMP, and COC																					

RAWP: Remedial Action Workplan FER: Final Engineering Report SMP: Site Management Plan COC: Certificate of Completion