SITE OBSERVATION REPORT

46-81 Metropolitan Avenue 46-81 Metro Ground Lessee LC c/o Prologis, Inc. WEATHER: Overcast/Rain, 40.0 – 50.0 °F Wind: NW @ 3.9 – 6.5 mph LOCATION: Queens, NY Image: State Comparison of the State Compar	PROJECT No.:	170663101	CLIENT:		DATE:	Wednesday, November 16, 2022	
BCP SITE ID: C241260 TIME: 6:45 am - 4:30 pm CONTRACTOR: Lakewood Environmental Services Corp. (Lakewood) LANGAN REP.: Liz McConnell EQUIPMENT: MiniRAZ 3000 PID DustTrak II Geoprobe® 6610DT Direct-Push Drill Rig PRESENT AT SITE: Langan (Environmental) - Liz McConnell Lakewood (Drilling Contractor) - Tim Kelly, Adam Hutchinson OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC: Langan continued implementation of the New York State Department of Environmental Conservation (NYSDEC)- approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC Brownfield Cleanup Program (BCP) Site No. C241260). Site Activities Lakewood used a Geoprobe® 6610DT direct-push drill rig to advance one soil boring in the eastern part of the site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples:	PROJECT:	Metropolitan			WEATHER:		
BCP SITE ID: C241260 CONTRACTOR: Lakewood Environmental Services Corp. (Lakewood) LaNGAN REP: Liz McConnell EQUIPMENT: MiniRAE 3000 PID DustTrak II PRESENT AT SITE: Remedial Investigation Day 05 Geoprobe® 6610DT Direct-Push Drill PRESENT AT SITE: Remedial Investigation Day 05 Langan (Environmental) – Liz McConnell Laegan (Environmental) – Liz McConnell Laegan (Environmental) OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.: Langan continued implementation of the New York State Department of Environmental Conservation (NYSDEC)- approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC) Brownfield Cleanup Program (BCP) Site No. C241260). Site Activities • SB27 was advanced to a depth of about 20 feet below grade surface (bgs) with 4-foot-long Macro- Core® samplers and decicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoinnizition detector (PID). No evidence of impacts were obsers, staining, and organic vapors using a photoinnitoring wells previously containing free product (ie. non-aqueous phase liquid (NAPL)). Montoring wells MW02, MW05, and MW24 (formenty MWV#9/G-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annuluus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal mathole cover set into concrete. 0 Lakewood developed each monintoring well by	LOCATION:	Queens, NY			TINAC.	0.45 and 4.20 mm	
CONTRACTOR: (Lakewood) Canual and the second and the s	BCP SITE ID:	C241260				6:45 am – 4:30 pm	
MiniRAE 3000 PID DustTrak II Geoprobe® 6610DT Direct-Push Diriti Langan (Environmental) – Liz McConnell Lakewood (Drilling Contractor) – Tim Kelly, Adam Hutchinson OBSERVATIONS, DISCUSSIONS, TEST RESULTS, ETC.: Langan continued implementation of the New York State Department of Environmental Conservation (NYSDEC)- approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC Brownfield Cleanup Program (BCP) Site No. C241260). Ste Activities Lakewood used a Geoprobe® 6610DT direct-push drill rig to advance one soil boring in the eastern part of the site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples: SB27 was advanced to a depth of about 20 feet below grade surface (bgs) with 4-foot-long Macro- Core® samplers and dedicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoinization detector (PID). Ne evidence of impacts were observed. Following sample collection, soil boring SB27 was backfilled with non-impacted soil cuttings and patched with cold patch asphalt to match the surrounding grade. Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-auguous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed uting a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete. Lakewood developed each monitoring we	CONTRACTOR:		nmental Services Cor	0.	LANGAN REP. : Liz McConnell		
 Langan continued implementation of the New York State Department of Environmental Conservation (NYSDEC): approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC) Brownfield Cleanup Program [BCP] Site No. C241260). Site Activities Lakewood used a Geoprobe® 6610DT direct-push drill rig to advance one soil boring in the eastern part of the site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples: 	MiniRAE 3000 P DustTrak II Geoprobe® 6610	MiniRAE 3000 PID DustTrak II Geoprobe® 6610DT Direct-Push Drill Lakewood (Drilling Contractor) – Tim Kelly, Adam Hutchinson					
 approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC Brownfield Cleanup Program [BCP] Site No. C241260). Site Activities Lakewood used a Geoprobe® 6610DT direct-push drill rig to advance one soil boring in the eastern part of the site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples: SB27 was advanced to a depth of about 20 feet below grade surface (bgs) with 4-foot-long Macro-Core® samplers and dedicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoinization detector (PID). No evidence of impacts were observed. Following sample collection, soil boring SB27 was backfilled with non-impacted soil cuttings and patched with cold patch asphalt to match the surrounding grade. Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete. Lakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in	OBSERVATION	S, DISCUSSIONS, T	EST RESULTS, ETC	.:			
 Lakewood used a Geoprobe[®] 6610DT direct-push drill rig to advance one soil boring in the eastern part of the site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples: SB27 was advanced to a depth of about 20 feet below grade surface (bgs) with 4-foot-long Macro-Core[®] samplers and dedicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoionization detector (PID). No evidence of impacts were observed. Following sample collection, soil boring SB27 was backfilled with non-impacted soil cuttings and patched with cold patch asphalt to match the surrounding grade. Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete. Lakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. 	Langan continued implementation of the New York State Department of Environmental Conservation (NYSDEC)- approved October 25, 2022 Remedial Investigation Work Plan (RIWP) at the 46-81 Metropolitan Avenue site (NYSDEC						
 site. Langan documented the work, screened the soil for environmental impacts, and collected soil samples: SB27 was advanced to a depth of about 20 feet below grade surface (bgs) with 4-foot-long Macro-Core® samplers and dedicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoionization detector (PID). No evidence of impacts were observed. Following sample collection, soil boring SB27 was backfilled with non-impacted soil cuttings and patched with cold patch asphalt to match the surrounding grade. Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring wells manhole cover set into concrete. Lakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized i	Site Activities						
Core® samplers and dedicated plastic liners. Material was screened for odors, staining, and organic vapors using a photoionization detector (PID). No evidence of impacts were observed. • Following sample collection, soil boring SB27 was backfilled with non-impacted soil cuttings and patched with cold patch asphalt to match the surrounding grade. • Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete. • Lakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. • Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Cc: M. Raygorodetsky, P. McMahon, M. Au By: Liz McConnell				•		•	
 Lakewood used a 6-inch-diameter auger to advance three boreholes to a depth of about 12 feet bgs adjacent to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete. Lakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Excess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Cc: M. Raygorodetsky, P. McMahon, M. Au By: Liz McConnell 	Core [®] samplers and dedicated plastic liners. Material was screened for odors, staining, and organic						
to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02, MW05, and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted metal manhole cover set into concrete.oLakewood developed each monitoring well by purging groundwater from the screened interval until the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility.oExcess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility.Cc:M. Raygorodetsky, P. McMahon, M. AuBy:Liz McConnell	0						
the purged groundwater was no longer turbid.Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility.oExcess soil generated during monitoring well reinstallation was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility.Cc:M. Raygorodetsky, P. McMahon, M. AuBy:Liz McConnell	to abandoned monitoring wells previously containing free product (ie. non-aqueous phase liquid [NAPL]). Monitoring wells MW02 , MW05 , and MW24 (formerly MW#9/GP-G, which was installed during a previous investigation) were reinstalled within the soil column of each respective borehole. The annulus of each monitoring well was backfilled using clean sand and the monitoring wells were finished with a flush-mounted						
55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate facility. Cc: M. Raygorodetsky, P. McMahon, M. Au By: Liz McConnell	the purged groundwater was no longer turbid. Groundwater generated from monitoring well development was containerized in a sealed and labeled, 55-gallon drum and staged in the eastern part						
	0	55-gallon drum and staged in the eastern part of the site pending off-site disposal to an appropriate					
	Cc: M. Rayo	jorodetsky, P. McMał	non, M. Au	By: Liz	z McConnell		
		·					

SITE OBSERVATION REPORT

Sampling Activities

- Langan collected four grab soil samples (plus quality assurance/quality control [QA/QC] samples) for laboratory analysis of target compound list (TCL) and NYSDEC Part 375-list volatile organic compounds (VOCs), semivolatile organic compounds (SVOCs), polychlorinated biphenyls (PCBs), pesticides, herbicides, NYSDEC Part 375-list and target analyte list (TAL) metals (including hexavalent chromium, trivalent chromium, and total cyanide), per- and polyfluoroalkyl substances (PFAS), and 1,4-dioxane.
- Samples were relinquished to York Analytical Laboratories Inc., an Environmental Laboratory Accredited Program (ELAP)-certified laboratory under standard chain-of-custody protocols.

CAMP Activities

Langan performed air monitoring in accordance with the community air monitoring plan (CAMP) for particulate matter less than 10 microns in diameter (PM10) and VOCs at upwind and downwind site perimeter locations. No PM10 or VOC concentrations exceeded the action levels established in the CAMP.

Particulate Mor	Organic Vapor Monitoring (ppm)				
Averaging Period	Upwind	Downwind	Averaging Period	Upwind	Downwind
Daily Time-Weighted Average	0.010	0.005	Daily Time-Weighted Average	0.0	0.0
Maximum 15-min Average	0.090	0.008	Maximum 15-min Average	0.0	0.0

mg/m³ = milligrams per cubic meter


ppm = parts per million

Anticipated Activities

• Langan and Lakewood will continue to advance soil borings for soil sampling in the northern and southern parts of the site.

Cc:	M. Raygorodetsky, P. McMahon, M. Au	By:	Liz McConnell
			LANGAN

SITE OBSERVATION REPORT



Langan PN: 170663101 Wednesday, November 16, 2022 Page 4 of 4

SITE OBSERVATION REPORT

Site Photographs:





Photo 1: Lakewood advancing soil boring SB27 in the eastern part of the site (facing northwest)



Photo 2: Lakewood developing monitoring well MW05 in the northwestern part of the site (facing northwest)

Cc:	M. Raygorodetsky, P. McMahon, M. Au	By:	Liz McConnell
			LANGAN



Air Monitoring Notes:

Sampling Notes:

Weather Notes:



