

Monthly Progress Report No. 15
990-1026 Rossville Avenue
Staten Island, NY 10309
Brownfield Cleanup Program Site No. C243043
Reporting Period: May 2022

1. Introduction

Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. (Langan) is submitting this monthly progress report on behalf of Allied Rossville LLC and in accordance with the 10 August 2020 Brownfield Cleanup Agreement (BCA). This monthly progress report summarizes work performed at 990-1026 Rossville Avenue (the "Site") for the month of May 2022.

The ±66,700-square-foot site is located at 990-1026 Rossville Avenue in Staten Island, New York and is identified as Block 7054, Lot 518 on the New York City Tax Map. The Site is bound to the north by three two-story residential buildings, to the east by Rossville Avenue followed by a two-story mixed-use residential/commercial building and a two-story residential building, to the south by Grafe Street followed by three two-story townhouse buildings associated with the Woodbrooke Estates residential community, and to the west by asphalt-paved tennis courts that are part of the Woodbrooke Estates residential community. The Site consists of a one-story shopping center that was constructed in 1990 and is currently occupied by a dry cleaner, liquor store, beauty salon, karate studio, ice cream parlor, grocery store, restaurant, bagel shop, laundromat, pizzeria, and a vacant former restaurant. A site location map is attached as Figure 1.

2. Remedial Actions Relative to the Site during this Reporting Period

Langan submitted the draft Remedial Action Work Plan (RAWP) to NYSDEC on 18 May 2022.

Langan remobilized to the site to perform the second monthly sub-slab depressurization system (SSDS) operation, maintenance, and monitoring (OM&M) inspection. Langan continued drafting the Construction Completion Report (CCR) for the SSDS.

3. Actions Relative to the Site Anticipated for the Next Reporting Period

Langan will continue to perform monthly SSDS OM&M activities.

4. Approved Activity Modifications (changes of work scope and/or schedule)

None

5. Results of Sampling, Testing and Other Relevant Data

None

6. Deliverables Submitted During This Reporting Period

Langan submitted the draft RAWP to NYSDEC on 18 May 2022.

7. Information Regarding Percentage of Completion

The BCP project is about 50% complete.

8. Unresolved Delays Encountered or Anticipated That May Affect the Schedule and Mitigation Efforts

None

9. Citizen Participation Plan Activities during This Reporting Period

None

10. Activities Anticipated in Support of the CPP for the Next Reporting Period:

None

11. Miscellaneous Information

None



Notes:
1. USGS Topographic basemap is provided through Langan's Esri ArcGIS software licensing and ArcGIS Online.
2. Parcel information from MapPLUTO 18v2 copyrighted by the New York City Department of Planning, last updated 2018.



<div><div>LANGAN</div><div>300 Kimball Drive Parsippany, NJ 07054 T: 973.560.4900 F: 973.560.4901 www.langan.com</div><div>Langan Engineering & Environmental Services, Inc. Langan Engineering, Environmental, Surveying, Landscape Architecture and Geology, D.P.C. Langan International LLC Collectively known as Langan</div><div>NJ CERTIFICATE OF AUTHORIZATION No. 24GA27996400</div></div>	<div>Project</div> <div>990-1026</div> <div>ROSSVILLE AVENUE</div> <div>BLOCK No. 7054, LOT No. 518</div> <div>CITY OF STATEN ISLAND</div> <div>RICHMOND COUNTY</div> <div>NEW YORK</div>	<div>Drawing Title</div> <div>USGS SITE</div> <div>LOCATION MAP</div>	Project No.	Figure
			100849501	1
			Date	
			2/25/2020	
			Scale	
			1" = 2,000'	
			Drawn By	
			KMB	