

Impact Environmental Engineering Geology, PLLC

170 Keyland Court | Bohemia | NY | 11716 | 631.269.8800 welcome to solid ground... www.impactenvironmental.com

DAILY STATUS REPORT #17

		WEATHER	Snow		Rain		Overcast	х	Partly Cloudy		Bright Sun	
Prepared By: Marius Sidlauskas		TEMP.	< 32		32-50		50-70	х	70-85		>85	
IEC Project No:	15514	NYSDEC BCP Site No:			C360211			Date:	1	10/26/2022		
Project:	Project: 60 McLean Avenue, Yonkers, NY											

Personnel On Site:						
Environmental Supervisor – Marius Sidlauskas (IEEG)						
Foreman – Javier Velasquez (SNL Construction)						
Demo Contractor – Frank Mazzurco (D-Best Industries)						

Scope of Work:

- Demolition of rear slab on second floor interior, air monitoring of dust and VOC's particles. Building walls will remain intact during rehabilitation work.
- Removal and offsite transport of slab rubble, to facilitate installation of new slab and bracing.

Site Activities:

• Non scope related (removing pipes, footings marked).

Community Air Monitoring Program (CAMP)

• IEEG did not implement work zone air monitoring due to no ground/soil disturbances.

Miscellaneous Items or Problem Encountered:

• None.

Planned Activities for the Next Day:


• Slab demo and excavation around footings (1st floor).



Impact Environmental Engineering Geology, PLLC

170 Keyland Court | Bohemia | NY | 11716 | 631.269.8800 welcome to solid ground... www.impactenvironmental.com

Site Activity Map





Impact Environmental Engineering Geology, PLLC

170 Keyland Court | Bohemia | NY | 11716 | 631.269.8800 welcome to solid ground... www.impactenvironmental.com

Photo Log

