



#### **REMEDIAL INVESTIGATION**

### **MONTHLY PROGRESS REPORT**

FOR
SOUTH SALINA STREET PARCELS
1081 SOUTH SALINA STREET
CITY OF SYRACUSE, ONONDAGA COUNTY, NEW YORK

#### **NYSDEC SITE No. C734140**

PROGRESS REPORT #25
REPORTING PERIOD: DECEMBER 2022

### Introduction

This progress report has been prepared to inform the NYS Department of Environmental Conservation ("NYSDEC") on the progress of the investigation of the South Salina Street Parcels Site in Syracuse, New York. The Site is in the Brownfield Cleanup Program.

# **Deliverables Completed and Submitted:**

None during the reporting period.

# **Work Completed During Reporting Period:**

• Stockpiled contaminated soil continues to be shipped offsite for landfill disposal. Approximately 1,800 tons were removed in December.

### **Work to be Completed Next Reporting Period:**

Contractor will continue to maintain security fence and erosion controls, and load out soil for disposal.

C&S will continue to provide full time construction observation and air monitoring.

### **Percentage Complete and Delays Encountered / Anticipated:**

The Remedial Investigation is complete.

Monthly Progress Report Page 2

Sincerely,

**C&S ENGINEERS, INC.** 

Mag 2 When

Matthew L. Walker

Senior Project Environmental Scientist

cc: file