



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 1307970  
 SPILL NAME: ROADWAY BY WAREHOUSE DEC LEAD: DBDAKE  
 SPILL DATE: 11/04/2013 SPILL TIME: 1:45 pm  
 CALL RECEIVED DATE: 11/04/2013 RECEIVED TIME: 1:49 pm

### SPILL LOCATION

PLACE: ROADWAY BY WAREHOUSE COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
 COMMUNITY: ROCHESTER  
 CONTACT: \_\_\_\_\_ CONTACT PHONE: \_\_\_\_\_

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Local Agency  
 FACILITY TYPE: Commercial/Industrial WATERBODY: \_\_\_\_\_

### CALLER REMARKS:

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
hydraulic oil	Petroleum	10 G		Imp Surf

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
vincent allan	10 mcnaur drive rochester NY 14624	vincent allan (585) 247-8961

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### DEC REMARKS:

11/4/13: DDAKE OF DEC SPILLS UNIT ONSITE APPROX. 1420 HOURS - OBSERVED A THIN/FEW INCHES WIDE STAINED TRAIL OF MOSTLY DRIED FLUID ON ROADWAY OF EXCHANGE STREET HEADING SOUTH FROM VIOLETT STREET APPROX, 100-YARDS +/- IN LENGTH. NEAR/IN FRONT OF #920 EXCHANGE STREET WAREHOUSE BUILDIN THERE ARE TWO MOSTLY DRIED PUDDLES OF FLUID (WHERE SKID STEER STOPPED). A CONTRACTOR (VINCEN' ALLAN) REPORTEDLY WORKING FOR THE PROPERTY OWNER (JOHN KAY & ASSOCIATES) COMES OUT OF #920 EXCHANGE ST BUILDING AND STATES THAT A FEW HOURS AGO HE BROKE A HYDRAULIC LINE ON A SKID STEER AND DIDN'T KNOW LINE WAS BROKEN, DRIPPING/TRAILING OIL ALONG ROADWAY AND EVENTUALLY STOPPING ( CONCRETE DRIVEWAY IN FRONT OF #920 BUILDING. THE TRAIL CONTINUES INTO THE BUILDING. THEY ARE REPORTEDLY WORKING FOR THE OWNER 'CLEANING UP THE BUILDING/REMOVING DEBRIS' AND WORKERS CAN BE SEEN PLACING DEBRIS IN A ROLLOFF. DEC DIRECTS ALLAN TO USE EITHER SALT OR SPEEDY DRY TO CLEAN UP POOLED AREAS AND TRAIL ON ROADWAY ASPHALT. ALLAN LEAVES AND RETURNS 40 MINUTES LATER WITH BAGS OF A WHITE POWDER/PETROLEUM CLEANUP MATERIAL, WHICH IS DUMPED ONTO THE IMPACTED AREAS, WORKED IN WITH BROOMS, AND SWEEPED UP. WASTE TO BE DOUBLE-BAGGED AND PLACED IN ROLLOFF FOR DISPOSAL (LIKELY LESS THAN 100 POUNDS). DDAKE OBSERVED CLEANUP IN FRONT OF #920 EXCHANGE ST ANI WORKERS BEGIN TO WORK ON TRAIL IN ROADWAY. SPILLS TO FOLLOWUP IN AM. DIGITAL PICS SAVED TO eDOCS.

Created On: 11/04/2013

Date Printed: 8/17/2018

Last Updated: 12/10/2013



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 1307970  
 SPILL NAME: ROADWAY BY WAREHOUSE DEC LEAD: DBDAKE

11/5/13: MIKE ZAMIARSKI OF SPILLS PERFORMS BRIEF SITE INSPECTION IN AM - POOLS OF OIL HAVE BEEN SOAKED UP. SOME MINOR STAINING ON ASPHALT ON ROADWAY, BUT ALL LIQUIDS HAVE BEEN COLLECTED. NO FURTHER ACTIONS REQUIRED BY SPILLS UNIT/SPILL FILE CLOSED.

PIN

T & A

COST CENTER

CLASS: C3      CLOSE DATE: 11/08/2013      MEETS STANDARDS: True



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 1601806  
 SPILL NAME: FORMER VACUUM OIL DEC LEAD: MFZAMIAR  
 SPILL DATE: 05/23/2016 SPILL TIME: 9:40 am  
 CALL RECEIVED DATE: 05/23/2016 RECEIVED TIME: 11:05 am

### SPILL LOCATION

PLACE: FORMER VACUUM OIL COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
 COMMUNITY: ROCHESTER  
 CONTACT: \_\_\_\_\_ CONTACT PHONE: \_\_\_\_\_

CONT. FACTOR: Other SPILL REPORTED BY: Local Agency  
 FACILITY TYPE: Commercial/Industrial WATERBODY: \_\_\_\_\_

**CALLER REMARKS:**  
 DURING A PHASE II, PETROLEUM ODORS, STAINING, AND ELEVATED PID READINGS WERE ENCOUNTERED.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
unknown petroleum	Petroleum			

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
EXXON MOBIL?	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure

### **DEC REMARKS:**

05/23/2016: GY TELECON WITH BIONDOLILLO. THEY WILL CONTINUE WITH THE PHASE II ESA. DRILLING IS EXPECTED TO CONTINUE FOR THE ENTIRE WEEK. SPILL ASSIGNED TO MIKE ZAMIARSKI FOR FOLLOW UP.

5/24/16 MZ ON SITE WITH STANTEC (LAURA BEST). THEY ARE ADVANCING BORINGS INSIDE BUILDING. SOME POINTS INSIDE BLDG SO FAR HAVE HAD LOW LEVELS IN SOILS. MORE TO BE INSTALLED INSIDE WEST PORTION OF BLDG (CLOSER TO FLINT STREET).

PIN                      T & A                      COST CENTER

CLASS: C3                      CLOSE DATE: \_\_\_\_\_                      MEETS STANDARDS: False



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9311324  
 SPILL NAME: EXCHANGE STREET DRUMS DEC LEAD: DLTILTON  
 SPILL DATE: 12/17/1993 SPILL TIME: 2:30 pm  
 CALL RECEIVED DATE: 12/20/1993 RECEIVED TIME: 9:00 am

### SPILL LOCATION

PLACE: EXCHANGE STREET DRUMS COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
BEHIND COMMUNITY: ROCHESTER  
 CONTACT: \_\_\_\_\_ CONTACT PHONE: \_\_\_\_\_

CONT. FACTOR: Abandoned Drums SPILL REPORTED BY: Local Agency  
 FACILITY TYPE: Unknown WATERBODY: \_\_\_\_\_

### **CALLER REMARKS:**

NINE 55-GHAL DRUMS ABANDONED BEHIND AN OLD WAREHOUSE. NO TOPS ON DRUMS; SOME HAVE BEEN KNOCKED OVER W/SLUDGE SPILLING TO GROUND.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
unknown petroleum	Petroleum	0 G	0 G	Soil,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
UNKNOWN	NY	

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### **DEC REMARKS:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "DT"  
 12/20/93: PROPERTY OWNER (ZORBA'S PALACE) OUT OF SALAMANCA, NY. GO DOWN EXCHANGE & VIOLETTA ST END OF ST BEHIND BLDGS. CONTRACTOR TO BE HIRED TO OVERPACK & DISPOSE OF DRUMS.  
 09/28/95: This is additional information about material spilled from the translation of the old spill file: ABANDONED DRUMS.  
 12/01/95 ALWASH HIRED TO SAMPLE, OVERPACK & DISPOSE. DRUM TAKEN TO IRA CONKLIN FOR DISPOSAL. DU TO BILLING MIXUP BETWEEN ALLWASH AND CONKLIN, TERRY RICH OF ALLWASH STATES THAT NO BILL FOR DISPOSAL WILL BE FORTHCOMING. NO FURTHER ACTION REQUIRED.  
 02/09/01: PAPER FILE REVIEWED AND RETAINED PER FILE RETENTION POLICY.  
 01/23/09: PAPER FILE REMOVED PER FILE RETENTION POLICY.

PIN T & A COST CENTER  
 H0051

Created On: 12/20/1993

Date Printed: 8/17/2018

Last Updated: 08/17/2018



# NYSDEC SPILL REPORT FORM



**DEC REGION:** 8 **SPILL NUMBER:** 9311324  
**SPILL NAME:** EXCHANGE STREET DRUMS **DEC LEAD:** DLTILTON  
**CLASS:** B3 **CLOSE DATE:** 12/21/1995 **MEETS STANDARDS:** False



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9870564  
 SPILL NAME: BEDDOE (PAUL) TRUCKING DEC LEAD: DLTILTON  
 SPILL DATE: 03/11/1999 SPILL TIME: 10:57 am  
 CALL RECEIVED DATE: 03/11/1999 RECEIVED TIME: 11:38 am

### SPILL LOCATION

PLACE: BEDDOE (PAUL) TRUCKING COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
 COMMUNITY: ROCHESTER  
 CONTACT: PAUL BEDDOE CONTACT PHONE: \_\_\_\_\_

CONT. FACTOR: Traffic Accident SPILL REPORTED BY: Health Department  
 FACILITY TYPE: Commercial Vehicle WATERBODY: \_\_\_\_\_

### CALLER REMARKS:

WHILE A TRUCK WAS BACKING UP, PAUL BEDDOE HAD HIS SADDLETANK RUPTURED, SPILLING DIESEL FUEL T  
 THE ASPHALT AND TO A STORM SEWER. MCPW IS AWARE. SPILL IS BEING CONTAINED. FIRE AND POLICE  
 DEPARTMENTS ON THE SCENE. MCHD TO UPDATE DEPARTMENT. FAXED TO MCHD ON 03/17/99 AT 1148 HRS.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	70 G	0 G	Sewer,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
PAUL BEDDOE	402 LEMMI ROAD LEMMI PA 19052-	PAUL BEDDOE

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "DT"  
 03/11/99 DT SPOKE WITH MCHD,(NATIONAL FREIGHT) THE TRUCKING FIRM THAT RAN INTO MR. BEDDOE TOOK O  
 RESPONSIBILITY FOR PROPER CLEANUP. EP&S WAS HIRED TO DO CLEANUP. ROCHESTER F.D. CR# 9905787 WA  
 FILED. E.P.&S. TO FORWARD DISPOSAL RECEIPTS TO MCHD AND WILL FORWARD TO THIS DEPARTMENT.

11/12/08: PAPER FILE REMOVED PER FILE RETENTION POLICY.

PIN                      T & A                      COST CENTER

CLASS: C3              CLOSE DATE: 03/11/1999              MEETS STANDARDS: False

Created On: 03/11/1999

Date Printed: 8/17/2018

Last Updated: 11/12/2008



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9970411  
 SPILL NAME: WAREHOUSING & DIST. DEC LEAD: MFZAMIAR  
 SPILL DATE: 10/01/1999 SPILL TIME: 12:01 pm  
 CALL RECEIVED DATE: 10/01/1999 RECEIVED TIME: 2:06 pm

### SPILL LOCATION

PLACE: WAREHOUSING & DIST. COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
 COMMUNITY: ROCHESTER  
 CONTACT: FRANK ARGENTO CONTACT PHONE: (716) 328-1000

CONT. FACTOR: Equipment Failure SPILL REPORTED BY: Other  
 FACILITY TYPE: Commercial Vehicle WATERBODY: \_\_\_\_\_

### CALLER REMARKS:

A TRACTOR TRAILER LOST 30 GALLONS OF DIESEL TO ASPHALT AND SOME TO A STORM SEWER. EP&S WAS HIRED TO CLEAN UP THE SPILL AND VACUUM OUT THE STORM SEWER. EP&S TO FORWARD DISPOSAL RECEIPTS TO THE DEPARTMENT. FAXED TO MCHD ON 10/01/1999 AT 1423 HRS.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	30 G	0 G	Sewer,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
DOCKWISE OPERATIONS	420 CANARCTIC DRIVE DOWNSVIEW, ONT. NN	IAN ARBICK (888) 739-5439

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### DEC REMARKS:

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "MZ"

PIN                      T & A                      COST CENTER

CLASS: C3              CLOSE DATE: 10/01/1999              MEETS STANDARDS: False



# NYSDEC SPILL REPORT FORM



DEC REGION: 8 SPILL NUMBER: 9970428  
 SPILL NAME: WAREHOUSING/DISTRIBUTING DEC LEAD: JRMARCHI  
 SPILL DATE: 10/15/1999 SPILL TIME: 9:30 am  
 CALL RECEIVED DATE: 10/15/1999 RECEIVED TIME: 10:00 am

### SPILL LOCATION

PLACE: WAREHOUSING/DISTRIBUTING COUNTY: Monroe  
 STREET: 920 EXCHANGE STREET TOWN/CITY: Rochester (c)  
 COMMUNITY: ROCHESTER  
 CONTACT: JIM NESTICO CONTACT PHONE: (716) 328-1000

CONT. FACTOR: Human Error SPILL REPORTED BY: Other  
 FACILITY TYPE: Commercial Vehicle WATERBODY: \_\_\_\_\_

### **CALLER REMARKS:**

A TRACTOR TRAILER RUPTURED ITS SADDLE TANK SPILLING 12-15 GALLONS OF DIESEL TO THE GROUND AT WAREHOUSING AND DISTRIBUTING OFFICES. SOME DIESEL HAS IMPACTED THE STORM SEWER AS WELL. EP&S HAS BEEN HIRED TO VAC OUT THE STORM SEWER, APPLY SPEEDY DRI AND DRUM UP THE WASTE. FAXED TO MCHD 10/18/99 AT 0900 HRS.

MATERIAL	CLASS	SPILLED	RECOVERED	RESOURCES AFFECTED
diesel	Petroleum	12 G	0 G	Soil,

### POTENTIAL SPILLERS

COMPANY	ADDRESS	CONTACT
REG INTEGRATE LOGISTICS	2299 KENMORE AVENUE BUFFALO NY 14207-	(716) 876-4645

Tank No.	Tank Size	Material	Cause	Source	Test Method	Leak Rate	Gross Failure
----------	-----------	----------	-------	--------	-------------	-----------	---------------

### **DEC REMARKS:**

Prior to Sept, 2004 data translation this spill Lead\_DEC Field was "JM"  
 08/14/2001 BASED ON REVIEW OF DATABASE, NO FURTHER ACTION IS NEEDED BY SPILLS.

<u>PIN</u>	<u>T &amp; A</u>	<u>COST CENTER</u>
CLASS: C4	CLOSE DATE: 08/14/2001	MEETS STANDARDS: False