

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • **Fax:** (716) 851-7226

Website: www.dec.ny.gov

INSPECTION REPORT

Site Number: C932164

Date: June 16, 2015

Site Name: 401, 402 & 430 Buffalo Ave

Location: Buffalo Ave Niagara Falls, Niagara
County

Project Manager: Nate Munley - Benchmark

Project Engineer: Benchmark/Turnkey

Job Phone: (c) 289-1072, (o) 716-85-0599

HEALTH & SAFETY: Level D

DESCRIPTION OF WORK PERFORMED:

MJH on site at 10558 hrs

Weather – T~70⁰F, mostly cloudy, Wind N @ 9 mph

No one on site

Took Photos

MJH left site at 1100 hrs

Attachments: photo's

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: June 16, 2015



