

New York State Department of Environmental Conservation

Division of Environmental Remediation, Region 9

270 Michigan Avenue, Buffalo, New York 14203-2915

Phone: (716) 851-7220 • Fax: (716) 851-7226

Website: www.dec.ny.gov

INSPECTION REPORT

Site Number: C932164

Date: October 23, 2015

Site Name: 401, 402 & 430 Buffalo Ave

Location: Buffalo Ave Niagara Falls, Niagara County

Project Manager: Nate Munley - Benchmark

Project Engineer: Benchmark/Turnkey

Job Phone: (c) 289-1072, (o) 716-85-0599

HEALTH & SAFETY: Level D

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1100 hrs 1035 hrs

Weather – T~45°F, Mostly Cloudy, Wind calm

Excavation and backfill at 402 Buffalo Ave is complete. Soil staging at 430 Buffalo Ave on going. Soil being worked into cover system

MJH left site at 1110 hrs

Attachments: photo's

Inspector's Name (Print): Michael J Hinton

Inspector's Signature:

Date: October 23, 2015





