

New York Department of Environmental Conservation
Division of Environmental Remediation
Region 9 Office-Buffalo



FIELD INSPECTION REPORT#5

Date: October 19, 2005 Wednesday
Site Name: Greif Bros. Facility
Site Number: V00334-9
Location: 2122 Colvin Blvd.
Tonawanda(T), Erie County
Project Manager: M.. Hinton Region 9
Consulting Engineer: ERM (for Greif Bros.)
Contractor: Pinto Construction Co.
Job Phone: 870-1407 (DEC cell)

Weather Conditions: partly sunny, 54°, W15-25

Description of Work Performed:

re-piped building drain line, removed concrete vault, dewatering excavations.

Items of Concern/Comments:

Job meeting will be 10/20 at 1000.

Intermittent odors noted from exposed soil. DEC will require odor control measures during excavation activities. Contractor will have those measures available on 10/24.

HFD mobilized steel sheeting to the site.

DEC requested that drain excavation remain open until ERM has results of sampling of previously excavated soil proposed for backfill.

HEALTH & SAFETY:

PPE: D

Is the PPE in conformance with the specifications? : y

Are atmospheric monitoring results at acceptable levels?: y

SITE VISITORS: M. Hinton

CONTRACTORS INFORMATION: Pinto Construction Co.

Subcontractors: Darling Construction Co.

Prime Contractors Hours Worked: 0700-1530

Subcontractors: n/a

EQUIPMENT:

JD 450 LC track hoe, CASE 580 RT backhoe, Komatsu PC 160 track hoe, Baker tanks

WORK FORCE:

ERM: 2

Pinto Construction Co.: 1 laborer, 1 operator

Darling Construction Co.: n/a

Inspector's Name: Jim Tuk _____ Sanitary Const. Insp. II

Date: 10/19/05

field: 1050-1150

Distribution: G. Sutton _____/file
M. Hinton _____ Via e-mail

Attachments: digital photos