INSPECTION REPORT

Site Number: V-00334-9/915525

Site Name: Grief Bros. Corporation

Location: 2122 Colvin Blvd, Tonawanda

Project Manager: Michael J. Hinton

Project Engineer: Jon Fox ERM

Job Phone: N/A

HEALTH & SAFETY: PPE: Level D

Is the PPE level in conformance with the specifications: N/A Are atmospheric monitoring results at acceptable levels? N/A

DESCRIPTION OF WORK PERFORMED:

MJH on site at 1115 hrs Weather –overcast, W Wind, T~55^oF

ERM – Jon Fox, Rob Sents, Jason Reynolds Pinto – 2 plumbers, 2 operators, 2 laborers and foreman

Old abandoned fire line being removed from excavation. Plumbers installing mechanical caps on remaining 8" DI pipe ends. Thrust blocks to be installed to secure caps.

ERM screened remaining soil in completed areas, all readings below 5 on PID meter.

West end remaining to be excavated, expect to have all areas excavated by the end of today.

Gravel backfill from permitted pit in Genesee County near Batavia. Data provided by Pinto does not indicate 80 sieve screen data. Pinto to re-run sieve analysis today to include 80 sieve data. ERM collected sample of gravel for possible chemical analysis if sieve analysis indicates >10% passing the 80 sieve.

Sub-Slab depressurization system running. Pressure problem traced to sensor that was reset. Sensor setting was to low to work with new carbon drum specs.

MJH left site at 1220hrs.

Attachments: Photo's

Inspector's Name (Print): Michael J. Hinton Inspector's Signature:

Date: May 25, 2011

Date: May 24, 2011



152511-01 Abandoned Fire Line.jpg



52411-03 Abandoned Fire Line.jpg



052411-05 West Side.jpg



052411-02 Abandoned Fire Line.jp(



152411-04 Abandoned Fire Line.jp

Greif Bros