

**TABLE 3
RESIDUAL SEDIMENT CONCENTRATIONS
CSXT - RIVER STREET DERAILMENT PROJECT
ROCHESTER, NY**

Sample ID	Sample Date	Acetone		Methylene Chloride	Comments
SS-19A 0.5'	12-Apr-05	200,000	U	1,200,000	
SS-19A 2'	12-Apr-05	4,000	U	12,000	
SS-19A 4'	12-Apr-05	3,300	U	1,300	
SS-88 0.5'	12-Apr-05	39	U	<i>34</i>	
SS-88 2'	12-Apr-05	7,400	U	52,000	
SS-88 4.5'	12-Apr-05	29	U	<i>180</i>	
SS-90 0.5'	12-Apr-05	3,800	U	2,400	Co-located with DC-4
SS-90 3'	12-Apr-05	73		<i>85</i>	
SS-90 6.5'	12-Apr-05	76		<i>17</i>	
SS-90 12'	12-Apr-05	4,100	U	1,300	Duplicate of SS-90 0.5'

Notes:

U= indicates compound was not detected at the stated limit

Bold face values indicate compound was detected above the cleanup criteria.

Italic face values indicate compound was detected but is not above the cleanup criteria.

All units are in ug/kg