

**Order: 01 - Compliance date: 08 November 2011 - Status: Complied
- Severity Code: Stop Use Order**

**for Reportable Incident regarding Gasfrac Energy Services LP. at LSD
7-27-50-20-W5 on 14 January 2011 at 16:45**

Order Number: 1
 Title: General - Equipment
 Level of Legislation: Regulations - Occupational Health And Safety Regulation (Alberta Regulation 62/2003)
 Under Part: 1 General
 Under Section: 12 Equipment
 Gazette/Year: AR 62/2003 Legal Reference: AR 62/2003 - 12
 Order Text:

COMMENTS:

A Gasfrac units
 2012, 2006, 2003, 1007, 3102, all units suffered fire and radiant heat damage in a fire/explosion at 7-27-50-20 W5. The current condition of the units is unknown to the employer.

REQUIREMENTS:

The unit cannot be used until the unit has been determined that it will safely perform the function for which it was intended and is free from obvious defects. This will require a Professional Engineer's certification for the unit in question. Teh units number was provided by Huskey Energy. Please confirm in writing that this is the same unit number and/or serial number for the gasfrac unit in question.

LEGISLATION:

12(1) An employer must ensure that all equipment used at a work site

(a) is maintained in a condition that will not compromise the health or safety of workers using or transporting it,

(b) will safely perform the function for which it is intended or was designed,

(c) is of adequate strength for its purpose, and

(d) is free from obvious defects.

(2) If a worker is required under the Act to use or wear specific equipment, the employer must ensure that the worker uses or wears the equipment at the work site.:

Severity Code: Stop Use Order
 Compliance Date: 14 January 2011
 Served Date: 15 January 2011
 Served Time: 01:00
 Extension Date:
 Compliance Achieved on: 08 November 2011

Status: Complied
 Suspension Reason:
 *Comments: The employer provided evidence of re-certification for the fire damaged

equipment. No further action is required.

File Reference: RGIT-805KRA

Client Contact Report Re-Inspection Report

CCR Reference Number: DMAH-SDSRFP-1



Occupational Health and Safety
North Region

10th Floor, 1003D - 107 Street,
South Tower
Edmonton, AB
T5J 3E4

780 422-8281

Employer Name (or Person) Gasfrac Services Gp Inc.		Employer Head Office Address	
Site Description 7-27-50-20 W5 Lease		City/Town/Municipality, Province , AB Country	Postal Code
Safety & Health Committee <input type="radio"/> Yes <input type="radio"/> No Phone Number: 403-340-3739 Fax Number:		Worksite Location (if different than above) LSD 7-27-50-20-W5 Edson, AB	
Rig Number		Employer's Representative/Title Ray Jeffrey, HSE Co-ordinator	
Number of Workers		Worker's Representative/Title	
Union or Association Name			

This report contains 1 order(s).

Order Number		Compliance Date	Severity Code
1	General - Equipment AR 62/2003 - 12 Comments: The employer provided evidence of re-certification for the fire damaged equipment. No further action is required.	08 November 2011 Complied	Stop Use Order

This report contains 1 order(s).

Comments:

This Reinspection Report was delivered by fax to: Ray Jeffrey, HSE Co-ordinator on 08 November 2011 at 07:35.

Signed:

Ted Lane - Occupational Health & Safety Officer

**THIS REPORT IS A PUBLIC DOCUMENT AND WILL BE RELEASED UPON REQUEST.
EMPLOYERS MUST POST THE REPORT IN A CONSPICUOUS PLACE READILY ACCESSIBLE TO WORKERS AT THE WORKSITE.**

**YOU HAVE THE RIGHT TO APPEAL ANY OF THE ORDERS IN ACCORDANCE WITH
SECTION 16 OF THE OCCUPATIONAL HEALTH & SAFETY ACT,
WITHIN 30 DAYS FROM THE DATE THE ORDER WAS SERVED.**

File Reference: RGIT-8D5KRA

Client Contact Report

CCR Reference Number: DHAH-8DSRFP



Occupational Health and Safety
North Region

10th Floor, Capital Health Centre
18050 - 107 Street, South Tower
Edmonton, AB
T5J 3E4

PHONE: 780 644-2660; FAX:
427-0693

Employer Name (or Person) Gasfrac Services Op Inc.	Employer Head Office Address	
Site Description 7-27-50-20 W5 Lease	City/Town/Municipality, Province , AB	Postal Code
Safety & Health Committee <input type="radio"/> Yes <input type="radio"/> No	Worksite Location (if different than above)	
Phone Number: 463-348-3739	LSD 7-27-50-20-W5	
Fax Number:	Edson, AB	
Rig Number:	Employer's Representative/Title	
Number of Workers:	Mike Langill, OHSE Manager	
Union or Association Name:	Worker's Representative/Title	

This report contains 1 order(s).

Order Number		Compliance Date	Severity Code
1	<p>General - Equipment AR 62/2003 - 12</p> <p>COMMENTS: A Gasfrac units 2012, 2008, 2003, 1007, 3102, all units suffered fire and radiant heat damage in a fire/explosion at 7-27-50-20 W5. The current condition of the units is unknown to the employer.</p> <p>REQUIREMENTS: The unit cannot be used until the unit has been determined that it will safely perform the function for which it was intended and is free from obvious defects. This will require a Professional Engineer's certification for the unit in question. Teh units number was provided by Muskey Energy. Please confirm in writing that this is the same unit number and/or serial number for the gasfrac unit in question.</p> <p>LEGISLATION: 12(1) An employer must ensure that all equipment used at a work site</p> <p>(a) is maintained in a condition that will not compromise the health or safety of workers using or transporting it,</p> <p>(b) will safely perform the function for which it is intended or was designed,</p>	14 January 2011	Stop Use Order

(c) is of adequate strength for its purpose, and		
(d) is free from obvious defects.		
(2) If a worker is required under the Act to use or wear specific equipment, the employer must ensure that the worker uses or wears the equipment at the work site.:		

This report contains 1 order(s).

Comments:

A STOP WORK ORDER given verbally on January 14, 2011 at approximately 5:30 p.m. for the location known as 7-27-60-20 WS has been lifted as of January 15, 2011 at 1:00 p.m. in order for the employer Gasfrac Services GP Inc. to begin recovery efforts. A LP purge procedure GFS-004 was provided to the Officer for review.

This Client Contact Report was delivered to: the attention of Mike Langill and Kyle Strandquist by Email on 15 January 2011 at 01:00.

Signed:

Danny Mah

Danny Mah - Occupational Health & Safety Officer

**THIS REPORT IS A PUBLIC DOCUMENT AND WILL BE RELEASED UPON REQUEST.
EMPLOYERS MUST POST THE REPORT IN A CONSPICUOUS PLACE READILY ACCESSIBLE TO WORKERS AT THE WORKSITE.**

YOU HAVE THE RIGHT TO APPEAL ANY OF THE ORDERS IN ACCORDANCE WITH SECTION 16 OF THE OCCUPATIONAL HEALTH & SAFETY ACT, WITHIN 30 DAYS FROM THE DATE THE ORDER WAS SERVED.

File Reference: RGIT-8D5KRA

Back

Assigned Officer: Ted Lane
 Sub-assigned Officers:
 Date Created: 15 January 2011
 Time Created: 08:07
 Date Received: 14 January 2011
 Time Received: 16:45
 Date Closed: 08 November 2011
 Time Closed: 07:39
 Status: Closed
 Time Spent: 0.00
 Assignment Number:

Back

Subject Information

Relationship to Site: Employer
 Company Common Name: Gasrac Energy Services LP
 Company Legal Name(s): Gasrac Energy Services Limited Partnership
 Company Alias:
 WCB Account Number: 664751
 WCB Industry Code/Description: Oilfield Downhole Services (9911)
 Common Business Identifier:
 Comments: [View COR](#)

Head Office Physical Address

Address: 850, 101-6th Ave SW
 Municipality: Calgary
 Province: AB Postal Code: T2P 3P4
 Country: Canada
 Contact: Malke Langill, QHSE Manager
 Phone Number: 780-340-3739 Fax Number:
 Cell Number:
 Email:

Head Office Mailing Address

Address: 850, 101-6th Ave SW
 Municipality: Calgary
 Province: AB Postal Code: T2P 3P4
 Country: Canada

Other Employer at Site

Relationship to Site: Owner
 Company Common Name: Husky Oil Operations Ltd.
 Company Legal Name(s): Husky Oil Operations Ltd.
 Company Alias:

WCB Account Number: 032769
 WCB Industry Code/Description: Refine Crude & Used Oil (35500), Service Stations (65400), Gas Bar/Car Wash - No Auto Service (85406), Oil/Gas-Exp/Dev Upstream Operations (6300)

Common Business Identifier:

Address: 707 8 Ave. SW
 Municipality: Calgary
 Province: AB Postal Code: T2P 1H5
 Country: Canada
 Contact: Kim Lester
 Phone Number: (403) 298-6111 Fax Number:
 Cell Number:
 Email:

Comments:

Back	Search	Location	Details
Inspection Location Information			
Location Name:		LSD 7-27-50-20-W5	
Address			
Address:		LSD 7-27-50-20-W5	
Municipality:		Edson	
Province:		AB Postal Code:	
Country:		Canada	
Contact			
Name/Title:		Mike Langill, OHSE Manager	
Phone Number:		403-340-3739 Fax Number:	
Cell Number:			
Email:			
WCB Account Number:		584751	
WCB Industry Code/Description:		Oilfield Downhole Services (9911)	
Number of Employees:			
Union/Association:			
Location Comments/Directions:			

Back	Search	Location	Details
------	--------	----------	---------

*Type of Service: Reportable Incident
 *Service Area: Occupational Health and Safety

Topic: Fire & Explosion Hazards, Oil & Gas Wells
Mode of Contact: Phone

Police/EMS File Number:
Region Involved: Edmonton

Details:

17(1) 17(4)(9)X) Tim Deschner, H&S Team Lead for Husky Services [redacted] and shortly afterwards Kyle Scrandquist H&S
17(1) 17(4)(9)X) Coordinator for Gasrac [redacted] notified about an incident at the site shown, where there was a fire due to a leak
on a propane frac truck. Three workers taken to Edson Hospital; uncertainty at time of call, as to severity of injuries.

Reportable Incident:

Incident Type: Fire / Explosion
Occurred On: 14 January 2011
Occurred At: 1540
Location Address: LSD 727-50-26-W5
Municipality: Edson
Contact at Location:
Time Dispatched: 17:00

File Reference: RGIT-8D5KRA